



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 BMW 520i**

**EXECUTIVE | 81,595 KM**

VIN: WBAJA1A00LBM53918

## **Car highlights**



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more





Basic Details

 Kilometers	81595	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBAJA1A00LBM53918		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Head Rest		Rear Defogger	
Central Armrest		Automatic Headlights	

Steering Column Adjuster	✓	
<div>  <b>Exteriors</b> </div>		
Fog Light Front	✓	Running Lights ✓
LED Headlights	✓	
<div>  <b>Performance</b> </div>		
Paddle Shift	✓	
<div>  <b>Safety &amp; Security</b> </div>		
Parking Sensors Front	✓	Parking Sensors Rear ✓
Auto Park Assist	✓	Reverse Camera ✓
Traction Control	✓	Airbag Curtain Shield ✓
Airbag Driver Front	✓	ABS ✓
Central Locking	✓	Child Safety Locking ✓
<div>  <b>Entertainment</b> </div>		
Bluetooth Player	✓	Infotainment System ✓
USB player	✓	





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Handle: Color/Chrome Dullness		Inner Handle: Color/Chrome Low Brightness	
Rear left door		Rear right door	

### Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	


### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
Roof Moulding Condition: Mounting Cap	
Unavailable	

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
RHS Pillar B Condition	✓	Right C Pillar Trim	✓
RHS Pillar C Condition	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Left D pillar	✓		
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
No structural damage			
Chassis Conditon	✓	Upper Cross Member Condition	✓
Lower Cross Member Condition	✓	Chassis Condition	✓
Radiator Support	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Alloy Wheel: Scratched		Alloy Wheel: Scratched	

Right Front Alloy/ Rim Alloy Wheel: Scratched	⚠	Right Rear Alloy/ Rim	✓
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel Scratched	⚠		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓
Transmission Operation	✓		

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel Condition: Trim Scratched	⚠	Shock absorbers	✓
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓

Brake Disc & Brake Pad



Brake Fluid



Suspension

Suspension



Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Remote Key Operations

Keyless/ Remote Start



Door Locks

Central Locking Operation



Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control



Heads Up Display



Infotainment Display



OBD Connector



Music System



Bluetooth Operations



Sunroof Operation

Sunroof



Lights

Lights



Running lights



Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Back Up Light



Fog Lights



Trunk Lid Release/Trunk Lid Light Operation







Air Conditioning



AC Air Direction Switch	✓	Blower Motor	✓
Compressor	✓	Condenser	✓
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	⚠	Heater	✓
Crack/Fair Use Wear			
AC Heater Operation Switch	✓	AC Blower Switch	✓
Rear Blower Switch	✓	AC Wind Direction	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	⚠
		Front Left: Master Switch Buttons Faded	
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	⚠	Sunvisors	✓
Steering Wheel Fair Use Wear			
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Seat Belt with issues	✓	Head Rest	✓
Door Controls And Trim	✓	Door Hinge Condition	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE