



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2015 BMW 520I**

**EXCLUSIVE | 88,048 KM**

VIN: WBA5A3108FD746116

## Car highlights



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**









Power driver seat, Memory Seats








## Basic Details

 Kilometers	<b>88048</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WBA5A3108FD746116</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
 <b>Exteriors</b>			
Fog Light Front			
 <b>Safety &amp; Security</b>			

Parking Sensors Front		Navigation	
Parking Sensors Rear		Reverse Camera	
 <b>Entertainment</b>			
USB Charging Port		Infotainment System	





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Scratch < 50mm		Panel: Light Scuffing < 50mm	


### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Scratch < 50mm	

### Front Bumper Condition

Front Bumper	
Condition: Misaligned	


### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm	

### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

### Trunk conditon

Trunk	
Lock: Faded	

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading Beading Crack/ Tear > 5mm	!
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield Scuffing > 50mm	!
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top Faded	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	!

Wiper 

Panel Condition

Rear Trunk Panel 

---

### Engine & Transmission

Engine

Engine Body 

Engine Performance 

Engine Oil (Condition & Level) 

Exhaust System 

Turbocharger/ Supercharger 

Radiator Condition 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting 

Drive Axle  
Rear Axle: Scratch 

Transmission Fluid 

---

### Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Disc & Brake Pad 

Brake Fluid 

Pedals 

Suspension

Shock Absorbers 



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control

Cruise Control Switch: Buttons Faded



Infotainment Display

Infotainment Display: Damaged Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



### Lights

Headlight

Left: Light Scuff Marks < 50mm, Beading Melted



Interior Lights

Door Entry Light: Cover Damaged



Tail Light Cluster

Right Tail Lamp: Light Scuffing < 50mm



Turn Signal Lights



Daylight Running Lights

Right DRL: Low Brightness



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent





Front Right AC Vent	✓	Heater	⚠
		Heater Not Working	
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	⚠
		Box: Lock Damage	
Cup Holder	✓	Glove Box	✓
Steering Wheel	⚠	Sunvisor	⚠
Steering Wheel Fair Use Wear		Left: Faded	
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	No spare tyre		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE