



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 VOLKSWAGEN TIGUAN

S | 76,478 KM

VIN: WVGAE2AX2JW402934

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Music System


Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats






Basic Details

 Kilometers	76478	 Specs	Yes
 Engine	1.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WVGAE2AX2JW402934		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Memory Seats	
Steering Mounted Audio Controls		Heads up Display	
 Exteriors			
Fog Light Front			
 Safety & Security			

Parking Sensors Front		Parking Sensors Rear	
 Entertainment			
USB Charging Port		Infotainment System	

150 Point Detailed Inspection Report





We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door		Front right door Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm	
Rear left door Panel: Low Visual Dent < 30mm		Rear right door	

Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm		Right Fender Condition: Light Scuffing < 50mm	
--	---	--	---

Quarter Panels Condition

Left Quarter Panel Condition: Chip<5mm		Right Quarter Panel Condition: Low Visual Dent < 30mm	
---	---	--	---

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper 
Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood 

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof 

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓

Wiper 

Panel Condition

Rear Trunk Panel 

Engine & Transmission

Engine

Engine Body 

Engine Performance 

Engine Oil (Condition & Level) 

Exhaust System 

Turbocharger/ Supercharger 

Radiator Condition 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting 

Gear shift 

Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Brake Performance 

Parking Brake 

Brake Master Cylinder 

Brake Disc & Brake Pad 

Brake Fluid 

Brake Calipers 

Pedals 

Suspension

Shock Absorbers 



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Air Direction Switch



AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Right AC Vent



Rear Defogger



USB Charging Port



















Power/ Manual Windows



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel Interior Dashboard Upholstery: Stain		Central Console	
Cup Holder		Glove Box	
Steering Wheel Steering Wheel Wear < 50mm		Sunvisor	
Seat Upholstery Driver Seat: Wear/ Fade Off < 50mm		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet Rear Right Floor Carpet: Stain < 80mm		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE