



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2018 FORD ECOSPORT AMBIENTE | 118,371 KM

VIN: MAJFK1BZ5JAE47174

## **Car highlights**



## **Good Tyre Condition**

Tyre age less than 2 years



#### **Bluetooth**

Enjoy your drive with bluetooth



## **Music System**


Enjoy your drive with music system



## **Amazing Comfort**


Power driver seat


#### **Basic Details**



## **Specs and features**

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





## **150 Point Detailed Inspection Report**


Trunk


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



#### Roof Pillars Condition Left A Pillar Right A Pillar Left A to B Pillar Beading Right A to B Pillar Beading Left B Pillar Right A to B Pillar Left B Pillar Trim Left B to C Pillar Beading Right B to C Pillar Right C Pillar Trim Light Scuffing < 80mm Left C Pillar Right B to C Pillar Beading Beading Crack/ Tear < 5mm Light Scuffing < 50mm **Running Board Condition** Right Running Board Left Running Board (!) (!) Front Right Sill Trim: Light Scuffing < 80mm Front Left Sill Trim: Minor Scuffing < 80mm Windshield Condition Front Windshield Condition: Driver Side/Stone Chip (!) Rear Windshield Mark<5mm, Passenger Side/Stone Chip Mark<8mm, Passenger Side/Light Scuffing<50mm Structural Assessment **Chassis Condition** Radiator Support **Boot Floor** Apron Door Skirting: Light Scuffing < 50mm Firewall Condition Cowl Top Head Light Support Condition Cowl Top Cowl Top Fair Use Wear/Crack<5mm Rear View Mirror Condition Left Hand Side Mirror Left Side Mirror Right Side Mirror Right Hand Side Mirror Alloy Wheel/ Rim

**Roof Condition** 





Dashboard And Instrument Panel	•	Central Console  Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	<b>✓</b>	Glove Box	<b>~</b>
Steering Wheel Steering Wheel Fair Use Wear	(!)	Sunvisor	•
Seat Upholstery	<b>✓</b>	Manual Seat Movement	•
Seat Belts	<b>✓</b>	Head Rest	•
Door Controls And Trim	<b>✓</b>	Grab Handle	<b>~</b>
Carpet Front Right Floor Mat: Smudge/Burn/Crack	(!)	Headliner	•
Rear View Mirror		Toolkit	
real view willer		. conta	
Tyres		. Contact	
		. Contac	
Tyres	•	Left Hand Side Rear Tyre	•
Tyres Condition	<ul><li>*</li><li>*</li></ul>		✓
Tyres  Tyres Condition  Left Hand Side Front Tyre	<ul><li></li><li></li><li></li><li></li><!--</td--><td>Left Hand Side Rear Tyre</td><td></td></ul>	Left Hand Side Rear Tyre	
Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre	<ul><li></li><li></li><li></li><li></li><!--</td--><td>Left Hand Side Rear Tyre</td><td></td></ul>	Left Hand Side Rear Tyre	
Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre	<75%	Left Hand Side Rear Tyre	<75%
Tyres  Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Tyres Depth (Remaining)		Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<75% <75%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE