



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 TOYOTA CAMRY

SE | 124,605 KM

VIN: 6T1BF9FK6HX692465

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort








Power driver seat

Basic Details

 Kilometers	124605	 Specs	Yes
 Engine	2.5L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	6T1BF9FK6HX692465		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience				
Cruise Control			Steering Mounted Audio Controls	
 Safety & Security				
Parking Sensors Rear			Reverse Camera	
 Entertainment				

USB Charging Port



Infotainment System





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

Exterior


Doors condition

Front left door		Front right door	
Handle: Light Scuffing < 50mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm		Handle: Scratch < 50mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm		Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Low Visual Dent<30mm, Light Scuffing<50mm, Acid Marks/ Bird Dropping<5mm		Glass: Beading Fair Use Wear/Disfiguration < 100mm	

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper 

Hood Condition

Hood
Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm, Dent > 30mm 

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof



Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading
Beading Crack/ Tear < 5mm



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Condition: Light Scuffing < 80mm



Right Running Board

Front Right Sill Trim: Light Scuffing < 80mm



Windshield Condition

Front Windshield

Condition: Air Bubbles



Rear Windshield

Light Scuffing < 50mm



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top
Beading: Crack/Fair Use Wear<50mm



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Light Scuffing < 50mm



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Paint Faded



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim




Rim: Paint Fade/Paint Defect		Rim: Alloy Edge/Scuffing<80mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Dent < 30mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight			
Left: Low Brightness lamps	!	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Color Dullness, Minor Scuffing/ Disfiguration/ Melted

Central Console

Cigarette Lighter: Cigarette Lighter Missing, Ashtray Missing

Cup Holder



Glove Box

Glove Box: Minor Scratches/Crack/Damage

Steering Wheel

Color Faded

Sunvisor



Seat Upholstery

Driver Seat: Minor Stain/ Cracks , Smudge/Cracks/Fair Use Wear>10 mm

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Stain

Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack

Headliner

Front Left: Light Smudge/Disfiguration

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre Crack/Uneven Wear

Left Hand Side Rear Tyre



Right Hand Side Front Tyre

Crack/Uneven Wear

Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre <55%

LHS Rear Tyre

<65%

RHS Front Tyre <65%

RHS Rear Tyre

<65%

Spare Tyre <85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE