



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 TOYOTA COROLLA

XLI | 40,679 KM

VIN: RKLBB0BE2M0038656

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort







Power driver seat

Basic Details

 Kilometers	40679	 Specs	Yes
 Engine	1.6L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	RKLBB0BE2M0038656		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience		
Cruise Control		Steering Mounted Audio Controls
		
 Safety & Security		
Parking Sensors Rear		
 Entertainment		

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door 
Inner Handle: Scratch

Front right door 
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door 
Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm


Rear right door 
Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm


Fenders Condition

Left Fender 
Condition: Paint Chip-off < 5mm

Right Fender 

Quarter Panels Condition


Left Quarter Panel 
Condition: Light Scuffing<50mm, Chip<5mm, Low Visual Dent<30mm

Right Quarter Panel 
Condition: Light Scuffing<50mm, Chip<5mm

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper 
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm, Scuffing > 80mm

Hood Condition

Hood 
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition


Roof 

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 


Right B to C Pillar 

Right B to C Pillar Beading 


Left C Pillar 

Running Board Condition

Left Running Board

Condition: Light Scuffing < 80mm, Scuffing > 80mm, Light Scuffing < 80mm, Scuffing > 80mm 

Right Running Board

Condition: Light Scuffing < 80mm, Light Scuffing < 80mm 

Windshield Condition

Front Windshield 

Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror

Body: Light Scuffing < 50mm, Chip < 5mm, Scuffing > 50mm 

Left Side Mirror 

Right Side Mirror

Body: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition 

Wheel Arch	✓	Wheel cover	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder	✓	Glove Box	⚠
		Glove Box: Scratch	
Steering Wheel	⚠	Sunvisor	✓
Scratch			
Seat Upholstery	⚠	Manual Seat Movement	✓
Driver Seat: Minor Stain/ Cracks			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE