



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 VOLKSWAGEN TIGUAN

R LINE | 120,196 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat


















Basic Details

 Kilometers	120196	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WVGCE2AX8FW500186		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Central Armrest		Automatic Headlights	
 Exteriors			
Fog Light Front		Roof Rails	

Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
 Safety & Security			
Navigation		Parking Sensors Front	
Parking Sensors Rear		Auto Park Assist	
Reverse Camera		Traction Control	
Airbag Curtain Shield		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Entertainment			
Bluetooth Player		Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Handle: Light Scuffing < 50mm



Rear left door

Panel: Dent < 30mm, Scratch < 50mm



Rear right door

Frame Extension Cover: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Scratch < 50mm, Dent < 30mm



Right Fender

Right Fender: Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Scratch < 50mm



Right Quarter Panel

Condition: Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Dent < 50mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber



Beading Fair Use Wear

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim Crack/Fair Use Wear	!	Left B to C Pillar Beading	✓
Right C Pillar Trim Light Scuffing	!	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Condition: Scratch < 80mm	!	Right Running Board Front Right Floor Trim: Light Scuffing < 80mm	!
---	---	--	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass Light Scuffing	!
----------------------------------	---

Windshield Condition

Front Windshield Condition: Passenger Side/Light Scuffing<50mm, Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
---	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top Cowl Top Fair Use Wear/Crack<5mm	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
------------	---	--------------	---

Door Locks

Child Safety Locking	✓		
----------------------	---	--	--

Dashboard

Instrument Panel	✓		
------------------	---	--	--

Airbags

Airbags	✓		
---------	---	--	--

Controls	✓	Cruise Control	✓
----------	---	----------------	---

Infotainment Display	✓	Engine Sensors	✓
----------------------	---	----------------	---

OBD Connector	✓	Navigation System	✓
---------------	---	-------------------	---

Music System	✓		
--------------	---	--	--

Sunroof Operation

Sunroof	✓		
---------	---	--	--

Camera	✓		
--------	---	--	--

Lights

Headlight Left: Light Scuff Marks < 50mm	⚠	Interior Lights	✓
---	---	-----------------	---

Tail Light Cluster Left Tail Lamp: Light Scuffing < 50mm	⚠	Turn Signal Lights	✓
---	---	--------------------	---

Daylight Running Lights	✓	License Plate Light	✓
-------------------------	---	---------------------	---

Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger Not Working	!	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓

Interiors & Luggage

Dashboard And Instrument Panel Goggle Holder: Color Dullness	!	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box Glove Box: Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off, Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<65%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE