



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 RENAULT SAFRANE

LE | 121,042 KM

VIN: VF1ABLC A3GC282789

Car highlights



Panoramic Roof

This car has a panoramic roof



Amazing Comfort
















Power driver seat



Tilt Steering wheel










Tilt steering wheel for extra comfort

Basic Details

 Kilometers	121042	 Specs	Yes
 Engine	3.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	VF1ABLCA3GC282789		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera			



Entertainment

USB Charging Port







150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

Front left door		Front right door Handle: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Scratch < 50mm, Paint Chip-off < 5mm	
--------------------	---	--	---

Front Bumper Condition

Front Bumper	
--------------	---


Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
Bonnet: Paint Damage/ Low Brightness, Low Visibility Dent < 30mm, Paint Chip-off < 5mm	

Trunk Condition

Trunk	
Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm	

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm	!		
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor			
Condition: Refurbished to RTA standards, Poor Refurb Job	!	Firewall Condition	✓
Cowl Top			
Beading: Crack/Fair Use Wear<50mm	!	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!

Light Scuffing < 50mm

Monogram



Window Glass

Rear Right Window Curtain: Fair Use Wear



Wiper



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System Condition: Available - SD Card Missing	!
Music System	✓		
Sunroof Operation			
Sunroof			
Curtain: Restricted Movement, Curtain Fair Use Wear	!		
Camera	✓		
Lights			
Headlight			
Left: Low Brightness lamps	!	Interior Lights	✓
Tail Light Cluster			
Right Tail Lamp: Crack / Fair Use Wear < 5mm	!	License Plate Light	✓
Fog Lights			
Right Fog Light: Light Scuff Marks < 50mm	!		
Air Conditioning			
AC Cooling	✓	AC Switch Button(s) Faded	!
AC System Leaks	✓	Center AC Vent Crack/Fair Use Wear	!
Front Right AC Vent Crack/Fair Use Wear	!	Heater	✓
Rear Blower Switch Heater Not Working	!		
Rear Defogger	✓	USB Charging Port	✓

Power/ Manual Windows
Rear Left: Switch Minor Color Faded/ Peel-Off



Seat Heaters
Left Front Seat: Seat Heater Not Working



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel
Dashboard Trim: Scuffing/Disfiguration



Central Console
Box: Minor Color Low Brightness, Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel
Steering Wheel Fair Use Wear



Sunvisor
Left: Sunvisor LHS Minor Disfiguration,
Sunvisor RHS Minor Disfiguration, Sunvisor
RHS Vanity Mirror Light Not Working,
Sunvisor LHS Vanity Mirror Light Not Working



Seat Upholstery
Driver Seat: Minor Smudge/ Cracks



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim
Front Right Door: Fair Use Wear



Grab Handle



Carpet
Front Left Floor Mat: Smudge/Burn/Crack



Headliner
Front Left: Crack/Fair Use Wear, Light Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre	<45%
------------	------



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE