



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 TOYOTA YARIS

SE / E | 140,678 KM

VIN: MHFB29F34H2022256

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort








Power driver seat

Basic Details

 Kilometers	140678	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	MHFB29F34H2022256		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience		
Cruise Control		
 Safety & Security		
Parking Sensors Rear		
 Entertainment		
USB Charging Port		Infotainment System 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

Exterior



Doors condition

Front left door		Front right door	
Inner Frame: Scratch < 50mm		Frame: Light Scuffing < 50mm	
Rear left door		Rear right door	
Handle: Paint Chip-off < 5mm, Scratch < 50mm		Handle: Scratch < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm, Scratch < 50mm		Right Fender: Scratch < 50mm, Paint Chip-off < 5mm	

Quarter Panels Condition


Left Quarter Panel		Right Quarter Panel	
Condition: Paint Chip-off < 5mm, Scratch < 50mm		Condition: Scratch < 50mm, Paint Chip-off < 5mm	

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Paint Chip-off > 5mm 

Trunk Condition

Trunk 


Trunk conditon

Trunk 

Roof Condition

Roof 

Pillars Condition


Left A Pillar
Condition: Paint chip-off < 5mm 

Right A Pillar
Condition: Chip<5mm 

Left A to B Pillar Beading 

Right A to B Pillar Beading 


Right A to B Pillar
Chip < 5mm 

Left B Pillar
Condition: Scratch < 50mm, Chip < 5mm 

Left B Pillar Trim 

Left B to C Pillar Beading 


Right C Pillar Trim 


Right B to C Pillar
Light Scuffing < 80mm 

Right B to C Pillar Beading 

Left C Pillar
Scratch < 50mm 

Running Board Condition

Left Running Board
Condition: Scratch < 80mm, Scuff < 80mm 

Right Running Board
Condition: Light Scuffing < 80mm, Light
Scuffing < 80mm 

Windshield Condition

Front Windshield 


Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor
Condition: Light Scuffing < 80mm 

Firewall Condition 


Cowl Top 

Head Light Support Condition 


Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror
Body: Paint Chip-off < 5mm 

Left Side Mirror 

Right Side Mirror
Body: Paint Chip-off < 5mm 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition 

Wheel Arch	✓	Wheel cover Front Right: Face/ Scuffs < 50mm, Edge/ Scuffs > 80mm	!
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) ✓
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Music System ✓
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster	✓	License Plate Light ✓
Air Conditioning		
AC Cooling	✓	AC Switch ✓
AC System Leaks	✓	Center AC Vent ✓
Front Right AC Vent	✓	Heater ✓
Parking Sensors	✓	Rear Defogger ✓
USB Charging Port	✓	Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE