



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2020 NISSAN MICRA S | 48,789 KM

VIN: MDHAK3CR7LG002429

# **Car highlights**



## **Low Mileage**

This car has been driven less than 15,000 km a year



## **Amazing Comfort**

Power driver seat



## **Tilt Steering wheel**


Tilt steering wheel for extra comfort

# **Basic Details**

Kilometers	48789	GCC	Specs	Yes
Engine	1.5L	( <del>*</del>	Option Type	Basic
Transmission	Automatic	1∲1 1⊕1	Drive	Front Wheel Drive
Body Type	НАТСНВАСК		Fuel	Petrol
Wheel Type	Steel Wheels		Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	*LO	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	R	Number of keys	2 Keys
OOO VIN number M	DHAK3CR7LG002429			

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>✓</b>	Right A Pillar	<b>✓</b>
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition  Left Running Board  Front Left Sill Trim: Minor Scuffing < 80mm	(!)	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition		1. 6.0: 1. M:	
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim  Spare Alloy/ Rim Condition			
Wheel Arch	<b>✓</b>	Wheel cover	<b>✓</b>
Antenna	<b>✓</b>	Grill Condition Light Scuffing < 50mm	!
Monogram	<b>✓</b>	Window Glass	<b>✓</b>
Wiper	<b>✓</b>		

Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Infotainment Display	•
Engine Sensors	<b>✓</b>	OBD Connector	<b>✓</b>
Music System Condition: EXTERNAL FITMENT	!	Camera Reverse Camera: External Fitment	(!)
Lights Headlight Left: Low Brightness lamps	!	Interior Lights	•
Tail Light Cluster	<b>✓</b>	License Plate Light	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch Missing Control Knob	!
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Defogger	<b>✓</b>	USB Charging Port Front: EXTERNAL FITMENT	(!)
Power/ Manual Windows	<b>✓</b>		
Interiors & Luggage			
Dashboard And Instrument Panel	<b>~</b>	Central Console Cigarette Lighter: Cigarette Lighter Missing	(!)
Cup Holder	<b>✓</b>	Glove Box	<b>✓</b>
Steering Wheel	<b>✓</b>	Sunvisor	•
Seat Upholstery	<b>✓</b>	Manual Seat Movement	<b>✓</b>
Seat Belts	<b>✓</b>	Head Rest	<b>✓</b>

Door Controls And Trim	<b>✓</b>	Grab Handle	<b>✓</b>
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	•
Rear View Mirror	<b>✓</b>	Toolkit	•
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	•
Spare Tyre	<b>✓</b>		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<55%
Spare Tyre	<75%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE