



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 TOYOTA FORTUNER

GXR | 99,481 KM

VIN: MHFYU59G2F7042999

Car highlights



Power packed

Engine size of 4.0 Litres & 6.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort







Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 99481 |  Specs | Yes |
|  Engine | 4.0L |  Option Type | Mid Option |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | MHFYU59G2F7042999 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Steering Mounted Audio Controls |  |
|  Exteriors | | | |
| Fog Light Front |  | | |
|  Safety & Security | | | |

Parking Sensors Rear



Reverse Camera



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Moulding: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing < 50 mm

Condition: Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



| | | | |
|---------------------------------|---|-------------------------------|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ! |
| | | Light Scuffing < 50mm | ! |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ! |
| Rim: Alloy Edge Scuffing < 80mm | ! | Rim: Alloy Edge/Scuffing>80mm | ! |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |

Wiper 

Panel Condition

Rear Trunk Panel 

Engine & Transmission

Engine

Engine Body 

Engine Performance 

Engine Oil (Condition & Level) 

Exhaust System 

Radiator Condition 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Cap 

Fuel Tank 

Transmission Operation

Gear Shifting 

Drive Axle 

4*4 Condition (If Applicable) 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Disc & Brake Pad 

Brake Fluid 

Pedals 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys













Master Key 

Spare Key(s) 

| | | | |
|-------------------------|---|---------------------|---|
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | Rear Left AC Vent | ✓ |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|--------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | |
| | | Gear Shift Knob: Minor wear and tear | ! |
| Cup Holder | ✓ | Glove Box | ✓ |

| | | | |
|--|---|----------------------|---|
| Steering Wheel Steering Wheel Fair Use Wear |  | Sunvisor |  |
| Seat Upholstery Driver Seat: Minor Fair Wear/Fade off |  | Manual Seat Movement |  |
| Seat Belts |  | Head Rest |  |
| Door Controls And Trim Rear Right Door: Scratch |  | Grab Handle |  |
| Carpet Front Right Floor Mat: Smudge/Burn/Crack |  | Headliner |  |
| Rear View Mirror |  | Toolkit |  |

Tyres

Tyres Condition

| | | | |
|----------------------------|---|---------------------------|--|
| Left Hand Side Front Tyre |  | Left Hand Side Rear Tyre |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre |  | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE