



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 SUZUKI JIMNY

GL | 62,896 KM

VIN: JS3JB7D11M5100158

Car highlights



Four wheel drive

This car has a Four wheel drive



Navigation

Navigation to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort







Power driver seat

Basic Details

 Kilometers	62896	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Manual	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Green
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	4 Seats	 Number of keys	2 Keys
 VIN number	JS3JB7D11M5100158		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors		
Fog Light Front		
 Safety & Security		
Navigation		
 Comfort & Convenience		
Steering Mounted Audio Controls		



Entertainment

Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm	

Fenders Condition

Left Fender		Right Fender	
		Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm, Acid Marks/	
Bird Dropping < 5mm	

Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

Trunk conditon

Trunk	
-------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Right C Pillar Trim	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓

Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓




Music System	✓	Camera	⚠
		Reverse Camera: External Fitment	
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard And Instrument Panel: Light Scuffing/Crack	⚠	Central Console	✓
Glove Box	✓	Steering Wheel	⚠
		Minor scratch	
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	⚠
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<75%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	<90%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE