



## **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

## **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2018 TOYOTA RAV4 EXR | 107,682 KM

# **Car highlights**



## Four wheel drive

This car has a Four wheel drive



## **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**


Enjoy your drive with bluetooth



# **Amazing Comfort**


Power driver seat

## **Basic Details**



# **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.






# **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel Arch	<b>✓</b>	Wheel cover	<b>✓</b>
Antenna	•	Grill Condition Light Scuffing < 50mm	(!)
Monogram	<b>✓</b>	Window Glass	<b>✓</b>



Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Cruise Control	<b>✓</b>
Infotainment Display	<b>✓</b>	Engine Sensors	<b>✓</b>
OBD Connector	<b>✓</b>	Music System	<b>✓</b>
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Turn Signal Lights	<b>✓</b>
Daylight Running Lights	<b>✓</b>	License Plate Light	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Parking Sensors	<b>✓</b>	Rear Defogger	<b>✓</b>
USB Charging Port	<b>✓</b>	Power/ Manual Windows	<b>✓</b>
🖺 Interiors & Luggage			
Dashboard And Instrument Panel	<b>✓</b>	Central Console	•
Cup Holder	<b>✓</b>	Glove Box	<b>✓</b>
Steering Wheel	<b>✓</b>	Sunvisor	•
Seat Upholstery	•	Manual Seat Movement	•

Seat Belts	<b>✓</b>	Head Rest	•
Door Controls And Trim	<b>✓</b>	Grab Handle	•
Carpet	•	Headliner	<b>✓</b>
Rear View Mirror	<b>✓</b>	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	<b>✓</b>		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE