



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 TOYOTA COROLLA**

**SE | 143,649 KM**

VIN: RKLBB9HE2K5232681

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat







Basic Details

 Kilometers	143649	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	RKLBB9HE2K5232681		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking		Child Safety Locking	
 <b>Entertainment</b>			
Bluetooth Player			
 <b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Beading: Fair Use Wear		Handle: Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Scratch < 50mm		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	


### Fenders Condition

Left Fender		Right Fender	
Condition: Dent < 30mm, Scratch < 50mm		Right Fender: Paint Chip-off < 5mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm		Condition: Acid Marks/ Bird Dropping > 5mm, Scratch < 50mm	

### Front Bumper Condition

Front Bumper	
Condition: Fair Use Wear	

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
------	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar Low Visual Dent < 30mm	!	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!
Running Board Condition			
Left Running Board Condition: Scuff < 80mm	!	Right Running Board Condition: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Right: Face/ Scuffs < 50mm	!
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓

Wiper	✓	
Panel Condition		
Rear Trunk Panel	!	
Dent < 30mm		

## Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
Transmission Fluid	✓	

## Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Pedals	✓	
Suspension		
Shock Absorbers	✓	

## Electricals, Controls & Lights

Keys		
------	--	--

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster			
Left Tail Lamp: Light Scuffing < 50mm	!	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks			
Temp In Running < 14°C	!	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder			
Rear Central: Broken/Fair Use Wear	!	Glove Box	✓



Steering Wheel Color Faded	⚠	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Rear Left Floor Carpet: Smudge / Fair Use Wear	⚠	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE