



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 LINCOLN NAVIGATOR

RESERVE | 44,447 KM

VIN: 5LMJJ2LT1KEL06450

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort









Power driver seat, Memory Seats

Basic Details

 Kilometers	44447	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	8 Seats	 Number of keys	2 Keys
 VIN number	5LMJJ2LT1KEL06450		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Panoramic Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display			
 Exteriors			
Fog Light Front			



Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Front Camera



Side Camera



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Scratch < 50mm

Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Light Scuffing < 50 mm

Condition: Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk








Roof Condition

Roof


















Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board		Right Running Board	✓
Front Left Sill Trim: Scratch < 80mm	!		
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top			
Fair Use Wear/Crack<5mm	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	!
		Rim: Alloy Edge/Scuffing<80mm	
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓

Grill Condition Light Scuffing < 50mm		Monogram	
Window Glass		Wiper	
Panel Condition Rear Trunk Panel Scratch < 50mm			

Engine & Transmission

Engine

Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		4*4 Condition (If Applicable)	
Transmission Fluid			

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Pedals 

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster

Right Tail Lamp: Crack / Fair Use Wear < 5mm



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE