



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2019 JEEP GRAND CHEROKEE

LIMITED | 36,895 KM

VIN: 1C4RJFBT9KC766969

### Car highlights



#### Power packed

Engine size of 5.7 Litres & 8.0 cylinders



#### Cruise control

Cruise control to drive with ease & comfort



#### Music System
















Enjoy your drive with music system



#### Amazing Comfort









Power driver seat, Memory Seats








Basic Details

 Kilometers	36895	 Specs	Yes
 Engine	5.7L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1C4RJFBT9KC766969		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> <b>Comfort &amp; Convenience</b></div>				
Panoramic Sunroof		<div></div>	Cruise Control	<div></div>
Memory Seats		<div></div>	Steering Mounted Audio Controls	<div></div>
<div><div></div> <b>Exteriors</b></div>				
Fog Light Front		<div></div>		
<div><div></div> <b>Safety &amp; Security</b></div>				

Parking Sensors Front 	Navigation 
Parking Sensors Rear 	Reverse Camera 
 <b>Entertainment</b>	
USB Charging Port 	Infotainment System 

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm	
-----------------	---	--	---

Rear left door Panel: Paint Chip-off < 5mm		Rear right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	
---	---	---	---

### Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm		Right Fender Condition: Paint Chip-off < 5mm	
--	---	---	---


### Quarter Panels Condition

Left Quarter Panel Condition: Chip<5mm		Right Quarter Panel Condition: Chip<5mm	
---	---	--	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

### Hood Condition

Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	
---	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Low Visual Dent < 30mm	!
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Paint Chip-off < 5mm	!	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!


Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  <b>Electricals, Controls &amp; Lights</b> </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights Right ORVM: Light Scuffing < 50mm	!
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓



Front Right AC Vent	✓	Heater	✓
Rear Left AC Vent	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓



## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE