



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 RENAULT TALISMAN

LE | 61,743 KM

VIN: VF1RFD009JC251594

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Seat massagers, Ventilated Seats





Basic Details

 Kilometers	61743	 Specs	Yes
 Engine	1.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	VF1RFD009JC251594		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Heads up Display		Climate Control AC	
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Rear Defogger	
Central Armrest		Seat Massagers	

Automatic Headlights	✓		
 Exteriors			
Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		
 Safety & Security			
Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Auto Park Assist	✓
Reverse Camera	✓	Blind Spot Monitor	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Performance			
Hydraulic Suspensions	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm



Right Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm, Colour Mismatch/ Low Brightness



Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm, Paint Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk




Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Colour Low
Brightness, Paint Peel-off 

Pillars Condition

Left A Pillar  Right A Pillar 

Left A to B Pillar Beading  Right A to B Pillar Beading 

Right A to B Pillar  Left B Pillar 

Left B Pillar Trim  Left B to C Pillar Beading 

Right C Pillar Trim  Right B to C Pillar 

Right B to C Pillar Beading  Left C Pillar 



Running Board Condition

Left Running Board  Right Running Board 
Front Left Sill Trim: Minor Scuffing < 80mm Front Right Sill Trim: Light Scuffing < 80mm

Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

Windshield Condition

Front Windshield
Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm  Rear Windshield 

Structural Assessment

Chassis Condition  Radiator Support 

Apron  Boot Floor 

Firewall Condition  Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror  Left Side Mirror 

Right Side Mirror  Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim
Rim: Alloy Face Light Scuffing < 50mm, Alloy
Edge Scuffing > 50mm



Left Rear Alloy/ Rim
Rim: Alloy Face Light Scuffing < 50mm, Alloy
Edge Scuffing > 50mm



Right Front Alloy/ Rim
Rim: Alloy Face Light Scuffing < 50mm, Alloy
Edge Scuffing < 80mm



Right Rear Alloy/ Rim
Rim: Alloy Face/Light Scuffing<50mm, Alloy
Edge/Scuffing<80mm



Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition
Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition
Rear Trunk Panel
Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Button Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls

Power Seat: Adjuster Switch Fair Use
Wear/Missing



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/
Fair Use Wear, Minor Scuffing/ Disfiguration/
Melted, Minor Color Dullness



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner Front Left: Headliner Loose	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
---------------------------	---	--------------------------	---

Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE