



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 MERCEDES BENZ GL 500

STD | 90,663 KM

VIN: WDCDF7DE3EA378906

Car highlights



Power packed

Engine size of 4.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat, Memory Seats & more

























Basic Details

 Kilometers	90663	 Specs	Yes
 Engine	4.6L	 Option Type	Full Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	WDCDF7DE3EA378906		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Power Head Rest	
Rear Defogger		Central Armrest	

Automatic Headlights			
 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		HID Headlights	
 Safety & Security			
Lane Departure Warning System		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Performance			
Paddle Shift		Hydraulic Suspensions	
 Entertainment			
Rear Seat Entertainment		Bluetooth Player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition


Front left door
Weather Strip: Light Scuffing < 50mm 

Front right door
Panel: Paint Chip-off < 5mm, Light Scuffing < 
50mm, Low Visibility Dent < 30mm

Rear left door
Panel: Paint Chip-off < 5mm, Light Scuffing < 
50mm

Rear right door
Panel: Paint Chip-off < 5mm, Light Scuffing < 
50mm


Fenders Condition

Left Fender
Condition: Light Scuffing < 50 mm, Paint
Chip-off < 5mm, Low Visual Dent < 30mm 

Right Fender 

Quarter Panels Condition

Left Quarter Panel
Condition: Low Visual Dent<30mm,
Chip<5mm, Light Scuffing<50mm 

Right Quarter Panel
Condition: Chip<5mm 

Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper
Rear Bumper: Dent < 50mm, Light Scuffing < 
80mm, Chip< 8mm

Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm, Acid Marks/
Bird Dropping < 5mm, Light Scuffing < 50mm 

Trunk Condition


Trunk
Door Trim: Scuff/ Disfiguration< 50mm, Light
Scuffing < 50mm 

Trunk conditon


Trunk	✓		
Roof Condition			
Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Light Scuffing < 50mm	⚠
Running Board Condition			
Left Running Board	⚠	Right Running Board	⚠
Front Left Floor Trim: Light Scuffing < 80mm		Right Foot Board: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm	⚠	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	⚠
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm 

Right Front Alloy/ Rim

Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing < 80mm 

Spare Alloy/ Rim Condition 

Wheel cover 

Grill Condition

Light Scuffing < 50mm 


Window Glass 

Panel Condition

Rear Trunk Panel

Paint Chip Off < 5mm 


Left Rear Alloy/ Rim

Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm 

Right Rear Alloy/ Rim

Rim: Alloy Face/Light Scuffing<50mm 


Antenna 

Monogram 

Wiper 

Engine & Transmission

Engine

Engine Body 

Engine Oil (Condition & Level) 

Turbocharger/ Supercharger 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Tank 


Transmission Operation

Gear Shifting 


Drive Axle 

Transmission Fluid 

Engine Performance 

Exhaust System 

Radiator Condition 

Gear shift 

4*4 Condition (If Applicable) 

Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad

Front Left: Brake Discs Light Rusting



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System

Condition: Available - SD Card Missing, Not Working



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Rear Entertainment	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Color Faded	!	Sunvisor Left: Sunvisor LHS Vanity Mirror Light Not Working	!
Seat Upholstery Driver Seat: Minor Fair Wear/Fade off, Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Right Door: Light Scuffing/Disfiguration	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<95%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE