



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MITSUBISHI PAJERO

GLS | 86,224 KM

VIN: JE4NR52RXKJ700714

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



















Basic Details

 Kilometers	86224	 Specs	Yes
 Engine	3.8L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JE4NR52RXKJ700714		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest			
 Exteriors			

Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
HID Headlights			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Moulding: Paint Chip-off < 5mm



Front right door
Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door
Moulding: Paint Chip-off < 5mm



Rear right door
Moulding: Paint Chip-off < 5mm, Light Scuffing < 50mm



Fenders Condition

Left Fender
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender
Condition: Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel
Condition: Light Scuffing<50mm, Chip<5mm



Right Quarter Panel
Condition: Chip<5mm, Light Scuffing<50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim Light Scuffing	!	Left B to C Pillar Beading	✓
Right C Pillar Trim Light Scuffing	!	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Front Left Floor Trim: Light Scuffing < 80mm	!	Right Running Board Front Right Floor Trim: Light Scuffing < 80mm	!
--	---	--	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass ✓

Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Door Skirting: Light Scuffing < 50mm	!
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top ✓

Rear View Mirror Condition

Left Hand Side Mirror Body: Chip < 5mm	!	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!
Right Front Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm	!	Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm	!

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	!	Monogram	!
Light Scuffing < 50mm		Light Scuffing < 50mm	
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓

Battery

Battery Terminal & Tightness	✓
------------------------------	---

Fuel System

Fuel Tank	✓
-----------	---

Transmission Operation

Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering

Steering wheel	✓
----------------	---

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓
--------	---

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight

Left: Condensation In Lamps, Low Brightness lamps



Interior Lights



Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent

LHS Crack/Fair Use Wear



Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	
		Front Right: Door Switch Minor Color Faded/Peel-off	!

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear	!	Box: Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	✓	Glove Box	
Steering Wheel		Glove Box: Glove Box Retainer Faulty, Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off	!	Head Rest	✓
Seat Belts	✓	Grab Handle	✓
Door Controls And Trim		Headliner	
Front Left Door: Fair Use Wear, Light Scuffing	!	Front Left: Light Smudge/Disfiguration	!
Carpet		Toolkit	✓
Trunk Floor Carpet: Fair Use Wear < 80mm	!		
Rear View Mirror	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE