



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 NISSAN X TRAIL

S | 138,362 KM

VIN: JN1BT2MW2FW001105

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Music System
















Enjoy your drive with music system



Amazing Comfort









Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|---------------------------|
|  Kilometers | 138362 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | JN1BT2MW2FW001105 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|------------------|---|
|  Exteriors | | | |
| Fog Light Front |  | Running Lights |  |
|  Comfort & Convenience | | | |
| Cruise Control |  | | |
|  Safety & Security | | | |
| Parking Sensors Rear |  | Traction Control |  |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Rear left door



Rear right door




Fenders Condition

Left Fender



Right Fender

Right Fender: Paint Chip-off < 5mm, Scratch < 50mm 

Quarter Panels Condition

Left Quarter Panel

Trim: Light Scuffing<80mm



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm



Trunk condition

Trunk



Roof Condition

Roof

Roof Moulding Condition: Colour fade



Pillars Condition

| | | | |
|--------------------------------|---|--|---|
| Left A Pillar | ⚠ | Right A Pillar | ⚠ |
| Inner Condition: Fair Use Wear | | Inner Condition: Light Scuffing | |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ⚠ |
| | | Beading Crack/ Tear < 5mm | |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | | Left C Pillar | ✓ |
| Beading Crack/ Tear < 5mm | ⚠ | | |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ⚠ |
| | | Rear Right Floor Trim: Light Scuffing < 80mm | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ⚠ |
| | | Beading: Crack/Fair Use Wear<50mm | |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Antenna | ✓ |

| | | | |
|------------------|---|----------|---|
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

Engine

| | | | |
|--------------------------------|---|--------------------|---|
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |

Battery

Battery Terminal & Tightness ✓

Fuel System

Fuel Tank ✓

Transmission Operation

Gear Shifting ✓ Drive Axle ✓

4*4 Condition (If Applicable) ✓ Transmission Fluid ✓

Steering, Suspension & Brakes

Steering

Steering wheel ✓

Brake System

Parking Brake ✓ Brake Master Cylinder ✓

Brake Disc & Brake Pad ✓ Brake Fluid ✓

Pedals ✓

Suspension

Shock Absorbers ✓

Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch

Crack



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows

















Interiors & Luggage

Dashboard And Instrument Panel



Central Console



| | | | |
|--|---|---|---|
| Cup Holder |  | Glove Box |  |
| Steering Wheel Color Faded |  | Sunvisor |  |
| Seat Upholstery Rear Right Seat: Smudge/Crack |  | Manual Seat Movement |  |
| Seat Belts |  | Head Rest |  |
| Door Controls And Trim Rear Left Door: Light Scuffing |  | Grab Handle |  |
| Carpet Front Left Floor Mat: Smudge/Burn/Crack |  | Headliner Front Left: Light Smudge/Disfiguration |  |
| Rear View Mirror |  | Toolkit |  |

Tyres

Tyres Condition

| | | | |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre |  | Left Hand Side Rear Tyre |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre |  | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <85% | RHS Rear Tyre | <85% |
| Spare Tyre | <55% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE