



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 RENAULT CAPTUR

SE | 64,777 KM

VIN: VF12RRJR5HW540404

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat











Basic Details

 Kilometers	64777	 Specs	Yes
 Engine	1.6L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF12RRJR5HW540404		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Rear Defogger	
Automatic Headlights			
 Exteriors			
Fog Light Front		Running Lights	

Halogen Headlights		
 Safety & Security		
Parking Sensors Rear		Traction Control 
Airbag Driver Front		ABS 
Central Locking		Child Safety Locking 
 Entertainment		
Bluetooth Player		

150 Point Detailed Inspection Report



We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm	

Rear left door		Rear right door	
Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm		Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Low Visual Dent<30mm, Light Scuffing<50mm		Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Low Visibility Dent < 30mm, Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition			
Roof	<div>✓</div>		
Pillars Condition			
Left A Pillar	<div>✓</div>	Right A Pillar	<div>✓</div>
Left A to B Pillar Beading	<div>✓</div>	Right A to B Pillar Beading	<div>✓</div>
Right A to B Pillar	<div>✓</div>	Left B Pillar	<div>✓</div>
Left B Pillar Trim	<div>✓</div>	Left B to C Pillar Beading	<div>✓</div>
Right C Pillar Trim	<div>✓</div>	Right B to C Pillar	<div>✓</div>
Right B to C Pillar Beading	<div>✓</div>	Left C Pillar	<div>✓</div>
Running Board Condition			
Left Running Board	<div>✓</div>	Right Running Board	<div>✓</div>
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	<div>!</div>	Rear Windshield	<div>✓</div>
Structural Assessment			
Chassis Condition	<div>✓</div>	Radiator Support	<div>✓</div>
Apron	<div>✓</div>	Boot Floor	<div>✓</div>
Firewall Condition	<div>✓</div>	Cowl Top	<div>✓</div>
Head Light Support Condition	<div>✓</div>		
Cowl Top			
Cowl Top	<div>✓</div>		
Rear View Mirror Condition			
Left Hand Side Mirror	<div>✓</div>	Left Side Mirror	<div>✓</div>
Right Side Mirror	<div>✓</div>	Right Hand Side Mirror	<div>✓</div>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<div>✓</div>	Left Rear Alloy/ Rim	<div>✓</div>
Right Front Alloy/ Rim	<div>✓</div>	Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm	<div>!</div>


Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Dent < 30mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel	!
		Steering Wheel Fair Use Wear	!
Sunvisor		Seat Upholstery	!
Left: Sunvisor LHS Vanity Mirror Cover	!	Rear Left Seat: Minor Smudge/ Crack	!
Damage, Sunvisor RHS Vanity Mirror Cover			
Damage			
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		



Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<40%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE