



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 CHEVROLET IMPALA**

**LT | 94,498 KM**

VIN: 2G1135S39K9107064

**Car highlights**



**Sunroof**

This car has a sunroof



**Cruise control**

Cruise control to drive with ease & comfort



**Bluetooth**
















Enjoy your drive with bluetooth



**Amazing Comfort**












Power driver seat, Memory Seats & more




Basic Details

 Kilometers	94498	 Specs	Yes
 Engine	3.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leatherette Trim	 Number of Airbags	12 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	2G1135S39K9107064		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Ventilated Seat	
Rear Defogger		Central Armrest	
Remote Engine Start		MagSafe Wireless Charging	

Automatic Headlights	✓		
 <b>Safety &amp; Security</b>			
Lane Departure Warning System	✓	Navigation	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Knees	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Exteriors</b>			
Running Lights	✓	HID Headlights	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior



### Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Dent < 30mm		Panel: Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm		Right Fender: Paint Chip-off < 5mm, Scratch < 50mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	

### Front Bumper Condition

Front Bumper	
--------------	---


### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	!	Right Running Board	!
Front Left Sill Trim: Scratch < 80mm		Front Right Sill Trim: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	⚠		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System

Condition: Remote Functions Not Responding



Sunroof Operation

Sunroof



### Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows





Seat Heaters	✓	Memory Seats	✓
--------------	---	--------------	---

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Arm Rest: Fabric Tear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<65%
RHS Front Tyre	<90%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE