



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2011 HONDA CR V**

**EX | 187,798 KM**

VIN: JHLRE4857BC401579

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Steering Mounted Audio Controls**
















Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**











Power driver seat

Basic Details

 Kilometers	187798	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Maroon
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JHLRE4857BC401579		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 <b>Exteriors</b>			
Fog Light Front		Halogen Headlights	



## Safety & Security

Parking Sensors Rear



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 


## Exterior

### Doors condition


Front left door   
Inner Frame: Scratch < 50mm

Front right door  
Moulding: Scuffing > 50mm, Paint Defect,   
Paint Chip-off < 5mm, Low Visual Dent < 30mm

Rear left door   
Frame: Scratch < 50mm


Rear right door  
Moulding: Scuffing, Low Visual Dent < 30mm,   
Paint Chip-off < 5mm


### Fenders Condition

Left Fender   
Condition: Scratch > 50mm, Dent < 30mm

Right Fender   
Right Fender: Scratch > 50mm, Dent < 30mm

### Quarter Panels Condition


Left Quarter Panel   
Condition: Dent < 30mm, Scratch > 50mm,  
Paint Chip-off < 5mm, Acid Marks/ Bird  
Dropping < 5mm

Right Quarter Panel   
Glass: Beading Fair Use Wear/Disfiguration > 100mm

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Light Scuffing < 80mm, Dent < 50mm, Chip< 8mm, Colour Mismatch/ Low  
Brightness 

### Hood Condition

Hood 

### Trunk Condition

Trunk   
Stay Condition: Shock Weak/ Leakage

### Trunk conditon

Trunk 

## Roof Condition

Roof

Roof Moulding Condition: Colour fade



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading

Beading Crack/ Tear > 5mm



Right A to B Pillar Beading



Right A to B Pillar

Low Visual Dent < 30mm



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading

Beading Crack/ Tear > 5mm



Left C Pillar



## Running Board Condition

Left Running Board

Condition: Chrome/ Rubber/ Plastic Fair Use  
Wear



Right Running Board

Condition: Chrome/ Rubber/ Plastic Fair Use  
Wear



## Sunroof Glass Condition (If Equipped)

Sun Roof Glass



## Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear >  
50mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Door Skirting: Colour Mismatch/ Fade/ Fair  
Use Wear



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror

Not Working Properly



Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Mirror Case Fair Use Wear			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	
		Broken/ Fair Use Wear	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering

Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Music System			
Steering Mounted Audio Controls: Button(s) Faded	!		
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight		Interior Lights	
Left: Low Brightness lamps, Cracks/ Holes	!	Front Map Reading Light: Front Map Reading Light not Working	!



Tail Light Cluster	!	Turn Signal Lights	✓
Left Tail Lamp: Crack / Fair Use Wear > 5mm			
License Plate Light	!	Fog Lights	✓
Number Plate Holder Fair Use Wear			
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	!
		Front Left: Master Switch Buttons Faded	

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear	!	Box: Minor Crack/Fair Use Wear/ Scuffing, Minor Color Low Brightness	!
Cup Holder	✓	Glove Box	✓
		Sunvisor	
Steering Wheel	✓	Left: Sunvisor RHS Vanity Mirror Light Not Working, Sunvisor RHS Vanity Mirror Cover Damage	!
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	!	Head Rest	✓
Driver Seat: Belt Not Returning Back			
Door Controls And Trim		Grab Handle	✓
Front Left Door: Light Scuffing/ Disfiguration, Fair Use Wear	!		
Carpet	✓	Headliner	
		Rear Left: Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE