



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN SUNNY

S | 66,534 KM

VIN: MDHBN7ADXJG628483

Car highlights



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Music System
















Enjoy your drive with music system



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	66534	 Specs	Yes
 Engine	1.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7ADXJG628483		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security				
Parking Sensors Rear			Traction Control	
Airbag Driver Front			ABS	
Central Locking			Child Safety Locking	
 Comfort & Convenience				
Steering Mounted Audio Controls			Rear Defogger	



Entertainment

Bluetooth Player



Exteriors

Halogen Headlights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm



Rear left door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Rear right door

Frame: Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Crack/ Misaligned



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar Condition: Chip < 5mm	!
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading Beading Crack/ Tear < 5mm	!	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	!	Right Running Board Condition: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Light Scuffing < 50mm	!	Left Side Mirror	✓
Right Side Mirror Body: Light Scuffing < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Left: Light Scuffing < 50mm	!

Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Dent < 30mm	!		

Engine & Transmission

Engine			
Engine Body Underbody: Minor Cover Fair Use Wear	!	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel Steering Wheel Fair Use Wear	⚠	Sunvisor	✓
Seat Upholstery Rear Right Seat: Smudge/Crack	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	⚠	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE