



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 TOYOTA RUSH**

**EX | 77,474 KM**

VIN: MHKEF8BF7KK002295

## **Car highlights**



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**

Enjoy your drive with bluetooth



### **Steering Mounted Audio Controls**
















Enjoy your drive with steering mounted audio controls



### **Amazing Comfort**






Power driver seat











Basic Details

 Kilometers	77474	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHKEF8BF7KK002295		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>			
Fog Light Front	<div></div>	Roof Rails	<div></div>
Rear Bumper Spoiler	<div></div>	Halogen Headlights	<div></div>
<div> Safety &amp; Security</div>			
Parking Sensors Rear	<div></div>	Traction Control	<div></div>
Airbag Curtain Shield	<div></div>	Airbag Driver Front	<div></div>

ABS		Central Locking	
Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Entertainment</b>			
Bluetooth Player		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front left door

Inner Handle: Color/Chrome Dullness



#### Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm



#### Rear left door

Frame: Scratch < 50mm



#### Rear right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm



### Fenders Condition

#### Left Fender

Condition: Light Scuffing < 50 mm, Acid Marks/ Bird Dropping < 5mm



#### Right Fender

Condition: Light Scuffing < 50mm



### Quarter Panels Condition

#### Left Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm



#### Right Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm



### Front Bumper Condition

#### Front Bumper



### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



### Hood Condition

#### Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



### Trunk Condition

#### Trunk



#### Trunk conditon

#### Trunk



## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Condition: Scratch < 50mm

Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Low Visual Dent < 50mm

Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



Front Left Floor Trim: Light Scuffing < 80mm

Condition: Light Scuffing < 80mm

## Windshield Condition

Front Windshield

Condition: Passenger Side/Stone Chip  
Mark<8mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Body: Paint Chip-off < 5mm

Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)

Missing Button



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage



Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor Left: Sunvisor RHS Vanity Mirror Cover Damage, Sunvisor RHS Vanity Mirror Light Not Working	!
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE