



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2011 FORD EDGE**

**SPORT | 188,440 KM**

VIN: 2FMDK4AK1BBA87892

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats

Basic Details

 Kilometers	188440	 Specs	Yes
 Engine	3.7L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	2FMDK4AK1BBA87892		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		Remote Engine Start	
Automatic Headlights			



## Performance

Paddle Shift



## Safety & Security

Parking Sensors Rear



Blind Spot Monitor



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Exteriors

Rear Bumper Spoiler



Halogen Headlights



## Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door  
Handle: Light Scuffing < 50mm 

Front right door  
Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door  
Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm 


Rear right door  
Handle: Paint Chip-off < 5mm, Scratch < 50mm 


### Fenders Condition

Left Fender  
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm 

Right Fender  
Condition: Light Scuffing < 50mm 

### Quarter Panels Condition

Left Quarter Panel  
Condition: Light Scuffing<50mm 

Right Quarter Panel  
Condition: Light Scuffing<50mm, Low Visual Dent < 30mm 

### Front Bumper Condition

Front Bumper 


### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Colour Mismatch/ Low Brightness, Paint Faded, Light Scuffing < 80mm 

### Hood Condition

Hood  
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 

### Trunk Condition

Trunk  
Door Trim: Light Scuffing < 50mm 

Trunk conditon

Trunk	✓		
Roof Condition			
Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Sunroof Not working	!		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			

Left Front Alloy/ Rim  
Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm



Right Front Alloy/ Rim  
Rim: Alloy Edge Scuffing < 80mm, Alloy Face Light Scuffing < 50mm



Spare Alloy/ Rim Condition



Wheel cover



Grill Condition  
Light Scuffing < 50mm



Window Glass



Panel Condition  
Rear Trunk Panel  
Scratch < 50mm



Left Rear Alloy/ Rim  
Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm



Right Rear Alloy/ Rim  
Rim: Alloy Edge/Scuffing<80mm, Alloy Face/Light Scuffing<50mm



Antenna  
Bent/Broken/Fair Use Wear/Missing



Monogram



Wiper



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	!	Spare Key(s)	!
Button Faded		Buttons Faded	
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera			
Reverse Camera: Lens Damaged/ Blurred, Feed not Proper	!		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓








Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim			
Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!	Grab Handle	✓
Carpet	!	Headliner	!
Front Left Floor Mat: Smudge/Burn/Crack		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	!	Toolkit	✓
Damaged Mirror Casing			

## Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<85%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE