



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2012 MITSUBISHI PAJERO

GLS MIDLINE | 216,568 KM

VIN: JMYLRV95WCJ706692

Car highlights



Four wheel drive

This car has a Four wheel drive



Sunroof

This car has a sunroof



Amazing Comfort

Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	216568	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	JMYLRV95WCJ706692		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Sunroof	
Steering Mounted Audio Controls	
 Exteriors	
Fog Light Front	
 Safety & Security	

Parking Sensors Rear		Reverse Camera	
Entertainment			
USB Charging Port		Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door



Rear right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Trim: Light Scuffing < 80mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board
Front Left Floor Trim: Light Scuffing < 80mm		Front Right Floor Trim: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		
Condition: Driver Side/Stone Chip		
Mark<5mm, Passenger Side/Stone Chip		Rear Windshield
Mark<8mm		
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
		Door Skirting: Light Scuffing < 50mm, Paint Chip-off < 5mm
Firewall Condition		Cowl Top
		Beading: Crack/Fair Use Wear>50mm
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Right Hand Side Mirror
Body: Not Folding		
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim

Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Broken/ Fair Use Wear	
Monogram	!	Window Glass	✓
Chrome Low Brightness/ Fair Use Wear			
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

🌐 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	!	Brake Master Cylinder	✓
Button Faded			
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight



Left: Low Brightness lamps

Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Center AC Vent



Crack/Fair Use Wear

Front Right AC Vent



Heater



Rear Left AC Vent



Rear Defogger



Extensive Wear Of Strip

LHS Crack/Fair Use Wear



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Scuffing/Disfiguration



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing, Lock Damage



Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor

Left: LHS Sunvisor Holder Crack/ Broken, RHS Sunvisor Holder Crack/ Broken



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle

Rear Left: Crack/Fair Use Wear



Carpet

Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear



Headliner

Rear Left: Smudge/Disfiguration, Light Scuffing



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE