



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 HYUNDAI I10

GL | 139,582 KM

VIN: MALAM51C3EM466503

Car highlights



Manufacturer warranty

Till 21/04/2023 or 2,589 km (Not Verified)



Amazing Comfort

Power driver seat



Airbag safety
















Airbag Driver Front



Tilt Steering wheel









Tilt steering wheel for extra comfort

Basic Details

 Kilometers	139582	 Specs	Yes
 Engine	1.2L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALAM51C3EM466503		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front 	Halogen Headlights 
 Comfort & Convenience	
Rear Defogger 	
 Safety & Security	
Airbag Driver Front 	ABS 

Child Safety Locking



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition



Front left door		Front right door Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm	
-----------------	-----------------------------------------------------------------------------------	-------------------------------------------------------------------------	-------------------------------------------------------------------------------------

Rear left door Panel: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm		Rear right door Handle: Scratch < 50mm	
----------------------------------------------------------------------------	-----------------------------------------------------------------------------------	-------------------------------------------	-------------------------------------------------------------------------------------


Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm, Scratch < 50mm		Right Fender Right Fender: Dent < 30mm, Scratch < 50mm	
----------------------------------------------------------------	-----------------------------------------------------------------------------------	-----------------------------------------------------------	-------------------------------------------------------------------------------------


Quarter Panels Condition

Left Quarter Panel Condition: Scratch < 50mm, Acid Marks/ Bird Dropping < 5mm, Dent < 30mm		Right Quarter Panel Condition: Scratch < 50mm, Paint Chip-off < 5mm	
-----------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	------------------------------------------------------------------------	---------------------------------------------------------------------------------------

Front Bumper Condition

Front Bumper Condition: Fair Use Wear	
------------------------------------------	-------------------------------------------------------------------------------------

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	
--------------------------------------------------------------	-------------------------------------------------------------------------------------

Hood Condition

Hood Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm, Paint Chip-off < 5mm	
----------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------

Trunk Condition

Trunk	
-------	-------------------------------------------------------------------------------------

Trunk conditon

Trunk	
-------	-------------------------------------------------------------------------------------

Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board

Condition: Scratch < 80mm, Scuff < 80mm



Right Running Board

Rear Right Sill Trim: Low Visibility Dent < 50mm, Light Scuffing < 80mm



Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear < 50mm



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Condition: Refurbished to RTA standards, Light Scuffing < 80mm



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top

Fair Use Wear/Crack<5mm



Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror

Body: Paint Chip-off < 5mm, Scratch < 50mm



Right Hand Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel cover

Front Right: Face/ Scuffs < 50mm, Edge/
Scuffs < 80mm



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm, Low
Brightness lamps



Interior Lights



Tail Light Cluster

Left Tail Lamp: Crack / Fair Use Wear < 5mm,
Light Scuffing < 50mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Glove Box	✓	Steering Wheel	!
		Steering Wheel Fair Use Wear	
Sunvisor	!	Seat Upholstery	!
Left: Sunvisor RHS Minor Smudge		Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	!
		Front Left Door: Light Scuffing/ Disfiguration	
Grab Handle	✓	Carpet	!
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner	!	Rear View Mirror	✓
Front Left: Light Smudge/Disfiguration			
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE