



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2015 TOYOTA FORTUNER

GXR | 100,835 KM

VIN: MHFYU59G0F7043679

### Car highlights



#### **Power packed**

Engine size of 4.0 Litres & 6.0 cylinders



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**
















Enjoy your drive with bluetooth



#### **Amazing Comfort**










Power driver seat




Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 100835            |  Specs             | Yes                  |
|  Engine           | 4.0L              |  Option Type       | Mid Option           |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MHFYU59G0F7043679 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Rear Defogger                   |  |
| Central Armrest  |  |                                 |   |
|  <b>Exteriors</b>                 |   |                                 |   |

|  |   |                      |   |
|--|---|----------------------|---|
| Fog Light Front  | ✓ | Roof Rails           | ✓ |
| Running Lights   | ✓ | Rear Bumper Spoiler  | ✓ |
| Halogen Headlights   | ✓ |                      |   |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Parking Sensors Rear   | ✓ | Reverse Camera       | ✓ |
| Airbag Driver Front  | ✓ | ABS                  | ✓ |
| Central Locking  | ✓ | Child Safety Locking | ✓ |
|  <b>Performance</b>           |   |                      |   |
| Differential Locks   | ✓ |                      |   |
|  <b>Entertainment</b>         |   |                      |   |
| Bluetooth Player   | ✓ | Infotainment System  | ✓ |
| USB player   | ✓ |                      |   |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|   |   |                  |   |
|---|---|------------------|---|
| Front left door                           |  | Front right door |  |
| Weather Strip: Minor Rubber Fair Use Wear |   |                  |   |
| Rear left door                            |  | Rear right door  |  |
| Weather Strip: Minor Rubber Fair Use Wear |   |                  |   |

### Fenders Condition

|   |   |                                  |   |
|---|---|----------------------------------|---|
| Left Fender   |   | Right Fender                     |   |
| Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm |  | Condition: Light Scuffing < 50mm |  |


### Quarter Panels Condition

|                    |   |                     |   |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|


### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper                                   |   |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

### Hood Condition

|                               |   |
|-------------------------------|---|
| Hood                          |   |
| Bonnet: Light Scuffing < 50mm |  |

### Trunk Condition

|                                  |   |
|----------------------------------|---|
| Trunk                            |   |
| Door Trim: Light Scuffing < 50mm |  |

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|   |   |   |   |
|---|---|---|---|
| Left A Pillar   | ⚠ | Right A Pillar  | ✓ |
| Inner Condition: Fair Use Wear                                    |   |   |   |
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading                                       | ✓ |
| Right A to B Pillar   | ✓ | Left B Pillar   | ✓ |
| Left B Pillar Trim  | ✓ | Left B to C Pillar Beading  | ✓ |
| Right C Pillar Trim   | ✓ | Right B to C Pillar   | ✓ |
| Right B to C Pillar Beading                                       | ✓ | Left C Pillar   | ⚠ |
|   |   | Low Visual Dent < 30mm  |   |
| Running Board Condition   |   |   |   |
| Left Running Board  | ⚠ | Right Running Board   | ⚠ |
| Front Left Sill Trim: Minor Scuffing < 80mm                       |   | Front Right Sill Trim: Light Scuffing < 80mm                      |   |
| Windshield Condition  |   |   |   |
| Front Windshield  | ✓ | Rear Windshield   | ✓ |
| Structural Assessment   |   |   |   |
| Chassis Condition   | ✓ | Radiator Support  | ✓ |
| Apron   | ✓ | Boot Floor  | ✓ |
| Firewall Condition  | ✓ | Cowl Top  | ✓ |
| Head Light Support Condition                                      | ✓ |   |   |
| Cowl Top  |   |   |   |
| Cowl Top  | ✓ |   |   |
| Rear View Mirror Condition  |   |   |   |
| Left Hand Side Mirror   | ✓ | Left Side Mirror  | ✓ |
| Right Side Mirror   | ✓ | Right Hand Side Mirror  | ✓ |
| Alloy Wheel/ Rim  |   |   |   |
| Left Front Alloy/ Rim   |   | Left Rear Alloy/ Rim  |   |
| Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm | ⚠ | Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm | ⚠ |
| Right Front Alloy/ Rim  |   | Right Rear Alloy/ Rim   |   |
| Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing < 80mm | ⚠ | Rim: Alloy Face/Light Scuffing<50mm                               | ⚠ |
| Spare Alloy/ Rim Condition  | ✓ |   |   |
| Wheel Arch  | ✓ | Wheel cover   | ✓ |

|                  |   |  |   |
|------------------|---|--|---|
| Antenna          | ✓ | Grill Condition<br>Light Scuffing < 50mm | ⚠ |
| Monogram         | ✓ | Window Glass                             | ✓ |
| Wiper            | ✓ |  |   |
| Panel Condition  |   |  |   |
| Rear Trunk Panel |   |  |   |
| Scratch < 50mm   | ⚠ |  |   |

## 🔧 Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Cap                       | ✓ | Fuel Tank          | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## 🚗 Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



### Camera



### Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows







## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light  
Scuffing/ Disfiguration/Melted, Light  
Scuffing/Crack



### Central Console

4X4 Shifting Knob: Knob Fair Use Wear



Cup Holder



Glove Box



### Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



### Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor  
Fair Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest



### Door Controls And Trim

Front Left Door: Fair Use Wear, Light Scuffing



Grab Handle



### Carpet

Front Left Floor Carpet: Smudge/Fair Use  
Wear



### Headliner

Rear Left: Light Scuffing



Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<90%

RHS Front Tyre

<65%

RHS Rear Tyre

<55%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE