



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 TOYOTA FORTUNER

GXR | 101,271 KM

VIN: MHFKU8FS9J0175924

Car highlights



Power packed

Engine size of 4.0 Litres & 6.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	101271	 Specs	Yes
 Engine	4.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MHFKU8FS9J0175924		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Rear Defogger	
Central Armrest		Automatic Headlights	
 Exteriors			

Fog Light Front	✓	Roof Rails	✓
Rear Bumper Spoiler	✓	Halogen Headlights	✓
 Performance			
Paddle Shift	✓	Differential Locks	✓
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Knees	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm		Rear right door Panel: Light Scuffing < 50mm	

Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm		Right Fender	
--	---	--------------	---

Quarter Panels Condition

Left Quarter Panel Condition: Light Scuffing<50mm		Right Quarter Panel Condition: Light Scuffing<50mm	
--	---	---	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm	
---	---

Hood Condition

Hood Bonnet: Paint Chip-off < 5mm	
--------------------------------------	---

Trunk Condition

Trunk Door Trim: Scuff/ Disfiguration< 50mm	
--	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	✓	Right A Pillar	⚠
		Condition: Low Visual Dent<30mm, Light Scuffing<50mm	
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	⚠	Left B Pillar	⚠
Low Visual Dent < 30mm		Condition: Chip < 5mm, Light Scuffing Scratch < 50mm	
Left B Pillar Trim	⚠	Left B to C Pillar Beading	✓
Light Scuffing			
Right C Pillar Trim	⚠	Right B to C Pillar	⚠
Light Scuffing		Low Visual Dent < 50mm	
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	⚠	Right Running Board	⚠
Condition: Light Scuffing < 80mm		Condition: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield	⚠	Rear Windshield	✓
Condition: Driver Side/Scuffing			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	⚠		
Fair Use Wear/Crack<5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	⚠	Left Side Mirror	✓
Body: Chip < 5mm			
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	⚠
Rim: Alloy Face Light Scuffing < 50mm		Rim: Alloy Face/Light Scuffing<50mm	
Spare Alloy/ Rim Condition	✓		


Wheel Arch	✓	Wheel cover Front Left: Paint Faded	!
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body			
Underbody: Minor Cover Fair Use Wear	!	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	4*4 Condition (If Applicable)	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight		Interior Lights	✓
Left: Light Scuff Marks < 50mm	!		
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	✓	USB Charging Port	!

Rear: minor imperfection

Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Central Console

Box: Minor Disfiguration



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery

Passenger Seat: Minor Smudge/Cracks



Manual Seat Movement



Seat Belts

Rear Center Seat Belt: Not Returning Back



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration, Light
Scuffing



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE