



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2019 NISSAN SUNNY

S | 177,660 KM

VIN: MDHBN7AD9KG650766

Car highlights



Great Parking Assistance

Parking Sensors Rear



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	177660	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7AD9KG650766		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Exteriors			
Halogen Headlights			



Entertainment

USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Colour Mismatch/ Low Brightness



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Condition: Paint Chip-off < 5mm, Low Visual Dent < 30mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	!	Right A Pillar	!
Inner Condition: Fair Use Wear		Inner Condition: Light Scuffing	
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Light Scuffing < 80mm		Left C Pillar	!
Right B to C Pillar Beading	✓	Scratch < 50mm	

Running Board Condition

Left Running Board	!	Right Running Board	!
Front Left Sill Trim: Scratch < 80mm		Front Right Sill Trim: Light Scuffing < 80mm	

Windshield Condition

Front Windshield		Rear Windshield	✓
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!		
Mark<8mm, Passenger Side/Light		Boot Floor	!
Scuffing<50mm		Condition: Light Scuffing < 80mm	

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	!
Firewall Condition	✓	Condition: Light Scuffing < 80mm	
Head Light Support Condition	✓	Cowl Top	✓

Cowl Top

Cowl Top	✓		
----------	---	--	--

Rear View Mirror Condition

Left Hand Side Mirror	✓	Right Side Mirror	✓
Right Hand Side Mirror	✓		

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition	✓		
----------------------------	---	--	--

Wheel Arch

Wheel cover	✓
-------------	---

Antenna	✓	Grill Condition Scuffing > 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls



Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights 

Tail Light Cluster



Left Tail Lamp: Crack / Fair Use Wear < 5mm

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater



Heater Not Working

Rear Defogger



Not Working

USB Charging Port 

Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ 

Fair Use Wear

Central Console



Box: Minor Crack/Fair Use Wear/ Scuffing

Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Color Faded			
Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	!
		Driver Seat: Fair Use Wear	
Door Controls And Trim			
Front Left Door: Light Scuffing, Light Scuffing/ Disfiguration	!	Grab Handle	✓
Carpet	!	Headliner	!
Front Left Floor Mat: Smudge/Burn/Crack		Front Left: Light Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE