



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 NISSAN KICKS

SV | 102,188 KM

Car highlights



Great Parking Assistance

Reverse Camera



Navigation

Navigation to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort





Power driver seat








Basic Details

 Kilometers	102188	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Orange
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3N1CP5C96HL497136		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Halogen Headlights			
 Safety & Security			
Navigation		Reverse Camera	
Traction Control		Airbag Driver Front	

ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Steering Mounted Audio Controls		Rear Defogger	
Automatic Headlights			
 Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door
Handle: Scratch < 50mm



Front right door
Handle: Paint Chip-off < 5mm



Rear left door
Handle: Scratch < 50mm



Rear right door
Panel: Light Scuffing < 50mm, Low Visual
Dent < 30mm



Fenders Condition

Left Fender
Condition: Dent < 30mm, Scratch < 50mm,
Paint Chip-off < 5mm



Right Fender
Right Fender: Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel
Condition: Scratch < 50mm



Right Quarter Panel
Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood
Bonnet: Paint Chip-off < 5mm, Acid Marks/
Bird Dropping < 5mm



Trunk Condition

Trunk
Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board Condition: Scratch < 80mm	!	Right Running Board Rear Right Floor Trim: Light Scuffing < 80mm	!
---	---	---	---

Windshield Condition

Front Windshield	✓	Rear Windshield Tint Fair Use Wear < 30mm	!
------------------	---	--	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!

Spare Alloy/ Rim Condition ✓

Wheel Arch ✓ Wheel cover ✓

Antenna	✓	Grill Condition	⚠
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Acid Marks/ Bird Dropping < 5mm	⚠		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel















Dashboard And Instrument Panel: Light Scuffing/Crack



Central Console

Cigarette Lighter: Cigarette Lighter Missing



Cup Holder		Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear		Left: Sunvisor LHS Minor Crack/Fair Use Wear, Sunvisor LHS Vanity Mirror Crack, Sunvisor RHS Minor Crack/Damage	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Front Left Door: Light Scuffing			
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE