



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 NISSAN X TRAIL**

**S | 84,875 KM**

VIN: JN1BT2MW3GW004774

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**









Power driver seat














## Basic Details

 Kilometers	<b>84875</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic Option</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>JN1BT2MW3GW004774</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>			
Fog Light Front		Running Lights	
Rear Bumper Spoiler		Halogen Headlights	
 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	

Central Armrest		
 <b>Safety &amp; Security</b>		
Parking Sensors Rear		Traction Control 
Airbag Driver Front		ABS 
Central Locking		Child Safety Locking 
 <b>Performance</b>		
Hill Descent Control		
 <b>Entertainment</b>		
Bluetooth Player		USB player 

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Rear left door

Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm



### Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm



Right Quarter Panel

Condition: Light Scuffing<50mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Low Visual Dent < 50mm	!
Right B to C Pillar Beading	✓	Left C Pillar Low Visual Dent < 30mm	!
Running Board Condition			
Left Running Board Front Left Sill Trim: Minor Scuffing < 80mm	!	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield Condition: Passenger Side/Light Scuffing<50mm, Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm, Alloy Face Light Scuffing < 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm	!

Right Front Alloy/ Rim  
Rim: Alloy Face Light Scuffing < 50mm



Right Rear Alloy/ Rim

Rim: Alloy Face/Light Scuffing<50mm, Alloy  
Edge/Scuffing<80mm



Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Paint Chip Off < 5mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid	✓
Pedals	✓
Suspension	
Shock Absorbers	✓



## Electricals, Controls & Lights

### Keys

Master Key ✓

### Door Locks

Child Safety Locking ✓

### Dashboard

Instrument Panel ✓

### Airbags

Airbags ✓

Controls ✓

Cruise Control ✓

Infotainment Display ✓

Engine Sensors ✓

OBD Connector ✓

Music System ✓

### Lights

Headlight  
Left: Light Scuff Marks < 50mm ⚠

Interior Lights ✓

Tail Light Cluster ✓

Turn Signal Lights ✓

Daylight Running Lights ✓

License Plate Light ✓

Fog Lights ✓

### Air Conditioning

AC Cooling ✓

AC Switch ✓

AC System Leaks ✓

Center AC Vent ✓

Front Right AC Vent ✓

Heater ✓

Rear Blower Switch ✓



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



Cup Holder



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE