



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 RENAULT KOLEOS**

**LE | 29,411 KM**

VIN: VF1HGRND6MC357068

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Seat massagers & more





Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 29411             |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | VF1HGRND6MC357068 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors  |  | Ventilated Seat                 |  |
| Power Tailgate/ Power Trunk  |  | Rear Defogger                   |  |
| Central Armrest  |  | Remote Engine Start             |  |

|   |   |                       |   |
|---|---|-----------------------|---|
| Seat Massagers  | ✓ | Automatic Headlights  | ✓ |
| <div>  <b>Exteriors</b> </div>             |   |                       |   |
| Fog Light Front   | ✓ | Roof Rails            | ✓ |
| Running Lights  | ✓ | LED Headlights        | ✓ |
| <div>  <b>Safety &amp; Security</b> </div> |   |                       |   |
| Navigation  | ✓ | Parking Sensors Front | ✓ |
| Parking Sensors Rear  | ✓ | Auto Park Assist      | ✓ |
| Reverse Camera  | ✓ | Blind Spot Monitor    | ✓ |
| Traction Control  | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front   | ✓ | ABS                   | ✓ |
| Central Locking   | ✓ | Child Safety Locking  | ✓ |
| <div>  <b>Performance</b> </div>         |   |                       |   |
| Hill Descent Control  | ✓ | Differential Locks    | ✓ |
| <div>  <b>Entertainment</b> </div>       |   |                       |   |
| Bluetooth Player  | ✓ | Infotainment System   | ✓ |
| USB player  | ✓ |                       |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |  |   |
|-----------------|---|--|---|
| Front left door |  | Front right door   |  |
|                 |   | Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm |   |

|                       |   |  |   |
|-----------------------|---|--|---|
| Rear left door        |  | Rear right door  |  |
| Panel: Scratch < 50mm |   | Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm |   |

### Fenders Condition

|   |   |  |   |
|---|---|--|---|
| Left Fender                                     |   | Right Fender                                       |   |
| Condition: Scratch < 50mm, Paint Chip-off < 5mm |  | Right Fender: Scratch < 50mm, Paint Chip-off < 5mm |  |

### Quarter Panels Condition

|  |   |                           |   |
|--|---|---------------------------|---|
| Left Quarter Panel                     |  | Right Quarter Panel       |  |
| Condition: Scratch < 50mm, Dent < 30mm |   | Condition: Scratch < 50mm |   |


### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|                                    |   |
|------------------------------------|---|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |   |

### Hood Condition

|  |   |
|--|---|
| Hood   |   |
| Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm |  |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|                                       |   |  |   |
|---------------------------------------|---|--|---|
| Roof                                  | ✓ |  |   |
| Pillars Condition                     |   |  |   |
| Left A Pillar                         | ✓ | Right A Pillar                                   | ✓ |
| Left A to B Pillar Beading            | ✓ | Right A to B Pillar Beading                      | ✓ |
| Right A to B Pillar                   | ✓ | Left B Pillar                                    | ✓ |
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading                       | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                              | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                                    | ✓ |
| Running Board Condition               |   |  |   |
| Left Running Board                    | ✓ | Right Running Board                              |   |
|                                       |   | Rear Right Sill Trim: Low Visibility Dent < 50mm | ⚠ |
| Sunroof Glass Condition (If Equipped) |   |  |   |
| Sun Roof Glass                        | ✓ |  |   |
| Windshield Condition                  |   |  |   |
| Front Windshield                      | ✓ | Rear Windshield                                  | ✓ |
| Structural Assessment                 |   |  |   |
| Chassis Condition                     | ✓ | Radiator Support                                 | ✓ |
| Apron                                 | ✓ | Boot Floor                                       | ✓ |
| Firewall Condition                    | ✓ | Cowl Top   | ✓ |
| Head Light Support Condition          | ✓ |  |   |
| Cowl Top                              |   |  |   |
| Cowl Top                              | ✓ |  |   |
| Rear View Mirror Condition            |   |  |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                                 | ✓ |
| Right Side Mirror                     | ✓ | Right Hand Side Mirror                           | ✓ |
| Alloy Wheel/ Rim                      |   |  |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                             | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                            | ✓ |

|                            |   |          |   |
|----------------------------|---|----------|---|
| Spare Alloy/ Rim Condition | ✓ |          |   |
| Wheel cover                | ✓ | Antenna  | ✓ |
| Grill Condition            | ✓ | Monogram | ✓ |
| Window Glass               | ✓ | Wiper    | ✓ |
| Panel Condition            |   |          |   |
| Rear Trunk Panel           |   |          |   |
| Scratch < 50mm             | ! |          |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch





|                   |   |                       |   |
|-------------------|---|-----------------------|---|
| Parking Sensors   | ✓ | Rear Defogger         | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |
| Seat Heaters      | ✓ |                       |   |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Tyres Depth (Remaining)    |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <75% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <65% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE