



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 NISSAN X TRAIL

S | 95,956 KM

VIN: JN1BT2MN4GH004712

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera



Bluetooth





Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat


Basic Details

 Kilometers	95956	 Specs	Yes
 Engine	2.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JN1BT2MN4GH004712		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Cruise Control 	Rear Armrest with cupholder 
Steering Mounted Audio Controls 	Rear Defogger 
Central Armrest 	
 Safety & Security	
Navigation 	Reverse Camera 

Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Exteriors			
Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
 Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Weather Strip: Low Visibility Dent < 30mm



Front right door



Rear left door

Panel: Low Visual Dent < 30mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition






Left A Pillar














Right A Pillar





Left A to B Pillar Beading Beading Crack/ Tear < 5mm		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim Light Scuffing		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board Front Left Sill Trim: Minor Scuffing < 80mm		Right Running Board	
Windshield Condition			
Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge Scuffing > 50mm		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim Rim: Alloy Edge Scuffing < 80mm		Right Rear Alloy/ Rim Rim: Alloy Face/Light Scuffing<50mm	
Spare Alloy/ Rim Condition			
Wheel Arch		Antenna	

Grill Condition Light Scuffing < 50mm		Monogram	
Window Glass		Wiper	
Panel Condition Rear Trunk Panel			

Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Brake Master Cylinder		Brake Disc & Brake Pad	
Brake Fluid			
Pedals			
Suspension			
Shock Absorbers			

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	✓	Camera	!
		Reverse Camera: Lens Damaged/ Blurred	
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster			
Right Tail Lamp: Crack / Fair Use Wear < 5mm	!	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	⚠
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	⚠	Manual Seat Movement	✓
Seat Belts Rear Left Seat: Smudge	⚠	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing	⚠	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	⚠	Headliner Front Left: Light Smudge/Disfiguration	⚠
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<40%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE