



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 MITSUBISHI MONTERO SPORT**

**GLS PREMIUM | 65,028 KM**

VIN: MMEMC71X7LH004126

## Car highlights



### **Great condition**

Car has low imperfections



### **Four wheel drive**

This car has a Four wheel drive



### **Amazing Comfort**
















Power driver seat



### **Tilt Steering wheel**










Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>65028</b>	 Specs	<b>Yes</b>
 Engine	<b>3.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>7 Airbags</b>
 Seating Capacity	<b>7 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MMEMC71X7LH004126</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Sunroof		Cruise Control	
Memory Seats		Steering Mounted Audio Controls	
Heads up Display		Cool Box	
 <b>Exteriors</b>			
Fog Light Front			



### Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Front Camera



Side Camera



### Entertainment

USB Charging Port



Infotainment System



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Trunk Condition

Trunk



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim	<input checked="" type="checkbox"/>	Left B to C Pillar Beading	<input checked="" type="checkbox"/>
Right C Pillar Trim	<input checked="" type="checkbox"/>	Right B to C Pillar	<input checked="" type="checkbox"/>
Right B to C Pillar Beading	<input checked="" type="checkbox"/>	Left C Pillar	<input checked="" type="checkbox"/>
Running Board Condition			
Left Running Board	<input checked="" type="checkbox"/>	Right Running Board	<input checked="" type="checkbox"/>
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	<input checked="" type="checkbox"/>		
Windshield Condition			
Front Windshield	<input checked="" type="checkbox"/>	Rear Windshield	<input checked="" type="checkbox"/>
Structural Assessment			
Chassis Condition	<input checked="" type="checkbox"/>	Radiator Support	<input checked="" type="checkbox"/>
Apron	<input checked="" type="checkbox"/>	Boot Floor	<input checked="" type="checkbox"/>
Firewall Condition	<input checked="" type="checkbox"/>	Cowl Top	<input checked="" type="checkbox"/>
Head Light Support Condition	<input checked="" type="checkbox"/>		
Cowl Top			
Cowl Top	<input checked="" type="checkbox"/>		
Rear View Mirror Condition			
Left Hand Side Mirror	<input checked="" type="checkbox"/>	Left Side Mirror	<input checked="" type="checkbox"/>
Right Side Mirror	<input checked="" type="checkbox"/>	Right Hand Side Mirror	<input checked="" type="checkbox"/>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<input checked="" type="checkbox"/>	Left Rear Alloy/ Rim	<input checked="" type="checkbox"/>
Right Front Alloy/ Rim	<input checked="" type="checkbox"/>	Right Rear Alloy/ Rim	<input checked="" type="checkbox"/>
Spare Alloy/ Rim Condition	<input checked="" type="checkbox"/>		
Antenna	<input checked="" type="checkbox"/>	Grill Condition	<input checked="" type="checkbox"/>
Monogram	<input checked="" type="checkbox"/>	Window Glass	<input checked="" type="checkbox"/>
Wiper	<input checked="" type="checkbox"/>		
Panel Condition			

Rear Trunk Panel



---

## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Cap



Fuel Tank



### Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



---

## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



---

## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Rear Entertainment	✓
Power/ Manual Windows	✓	Memory Seats	✓



Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE