



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 RENAULT DUSTER**

**SE | 148,414 KM**

VIN: VF1HSRMX1KA468016

## Car highlights



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

360° camera, Front Camera & more



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat

## Basic Details

 Kilometers	<b>148414</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Beige</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>VF1HSRMX1KA468016</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
360 degree Camera		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Front Camera		Side Camera	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



### Comfort & Convenience

Climate Control AC



Cruise Control



Steering Mounted Audio Controls



Central Armrest



Remote Engine Start



### Exteriors

Fog Light Front



Roof Rails



Running Lights



Halogen Headlights



### Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Frame: Acid Marks/ Bird Dropping < 5mm

Rear left door



Rear right door



Frame: Acid Marks/ Bird Dropping < 5mm

Frame: Acid Marks/ Bird Dropping < 5mm

### Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm

### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm

### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



### Trunk condition

Trunk



### Roof Condition

Roof

Roof Moulding Condition: Minor Rubber



Beading Fair Use Wear

Pillars Condition

Left A Pillar	✓	Right A Pillar Inner Condition: Light Scuffing	!
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	✓	Right Running Board Front Right Sill Trim: Low Visual Dent < 50mm	!
--------------------	---	--	---

Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top	✓
----------	---

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Paint Chip-off < 5mm	!	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights

Right DRL: Low Brightness



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger

Extensive Wear Of Strip



USB Charging Port




Power/ Manual Windows






## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear 

### Central Console

Cigarette Lighter: Cigarette Lighter Missing 

Cup Holder 


Glove Box 


### Steering Wheel


Steering Wheel Fair Use Wear 

Sunvisor 

### Seat Upholstery

Driver Seat: Minor Cigarette Burn, Minor Smudge/ Cracks, Minor Fair Wear/Fade off 


Manual Seat Movement 

Seat Belts 


Head Rest 

### Door Controls And Trim


Front Left Door: Light Scuffing/ Disfiguration 

Grab Handle 

### Carpet

Front Left Floor Mat: Smudge/Burn/Crack 

### Headliner

Front Left: Light Smudge/Disfiguration, Crack/Fair Use Wear 

Rear View Mirror 

Toolkit 

## Tyres

### Tyres Condition

Left Hand Side Front Tyre 

Left Hand Side Rear Tyre 

Right Hand Side Front Tyre 

Right Hand Side Rear Tyre 

Spare Tyre 

### Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE