



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 BMW 440i**

**M SPORT | 130,291 KM**

**VIN: WBA4T9106H5A14043**

## **Car highlights**



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Memory Seats

## Basic Details

 Kilometers	<b>130291</b>	 Specs	<b>Yes</b>
 Engine	<b>3.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>CONVERTIBLE</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Blue</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>4 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WBA4T9106H5A14043</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Heads up Display	
Cruise Control	
Steering Mounted Audio Controls	
Rear Defogger	
Automatic Headlights	
Climate Control AC	
Memory Seats	
Power Folding Mirrors	
Central Armrest	



## Exteriors

Fog Light Front	✓	Running Lights	✓
LED Headlights	✓		



## Safety & Security

Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Traction Control	✓
Side Camera	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓



## Performance

Paddle Shift	✓		
--------------	---	--	--



## Entertainment

Bluetooth Player	✓	Apple Play	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender

Right Fender: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm



Condition: Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Refurbished to RTA standards

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	!
Left B Pillar Trim	!	Condition: Dent < 30mm	
Crack/Fair Use Wear	!	Right C Pillar Trim	!
Running Board Condition		Fair Use Wear	
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	!
		Windshield Beadings > 50mm	
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	!
		Rim: Alloy Face/ Scuff < 50mm	
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		

## Panel Condition

Rear Trunk Panel

Scratch < 50mm



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control

Cruise Control Switch: Buttons Faded



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Camera

Left Camera: Lens Damaged/Blurred



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights

Right DRL: Low Brightness



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent

Fair Use Wear



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Seat Heaters



Memory Seats



 **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Scuffing/Crack	!	Box: Minor Color Low Brightness, Minor Disfiguration	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	
Steering Wheel Fair Use Wear		Left: Sunvisor RHS Vanity Mirror Light Not Working	!
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	!		
Seat Belts	!	Head Rest	✓
Rear Left Seat: Smudge			
Door Controls And Trim		Carpet	✓
Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!		
Headliner		Rear View Mirror	✓
Rear Left: Smudge/Disfiguration, Fair Use Wear	!		
Toolkit	✓		

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<90%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	No spare tyre		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE