



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 TOYOTA COROLLA

GLI | 135,160 KM

VIN: RKLBL9HE5F5229843

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Steering Mounted Audio Controls
















Enjoy your drive with steering mounted audio controls



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 135160 |  Specs | Yes |
|  Engine | 1.8L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Leather Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 1 Keys |
|  VIN number | RKLBL9HE5F5229843 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | | |
|--|--|--|-----------------------------|--|
| <div> Exteriors</div> | | | | |
| Fog Light Front | | <div></div> | Running Lights | <div></div> |
| Halogen Headlights | | <div></div> | | |
| <div> Comfort & Convenience</div> | | | | |
| Cruise Control | | <div></div> | Rear Armrest with cupholder | <div></div> |
| Steering Mounted Audio Controls | | <div></div> | Power Folding Mirrors | <div></div> |

| | | |
|--|---|---|
| Central Armrest |  | |
|  Safety & Security | | |
| Parking Sensors Rear |  | Airbag Driver Front  |
| ABS |  | Central Locking  |
| Child Safety Locking |  | |
|  Entertainment | | |
| USB player |  | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|------------------------------|---|------------------|---|
| Front left door |  | Front right door |  |
| Handle: Paint Chip-off < 5mm | | | |

| | | | |
|----------------|---|-----------------------------|---|
| Rear left door |  | Rear right door |  |
| | | Panel: Paint Chip-off < 5mm | |

Fenders Condition

| | | | |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|

Quarter Panels Condition

| | | | |
|---------------------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Condition: Paint Chip-off < 5mm | | | |


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

| | |
|---|---|
| Hood |  |
| Bonnet: Acid Marks/ Bird Dropping < 5mm | |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
|----------------------------|---|-----------------------------|---|

| | | | |
|---|---|-----------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| Front Left Sill Trim: Scratch < 80mm | ! | Condition: Light Scuffing < 80mm | ! |
| Windshield Condition | | | |
| Front Windshield | | Rear Windshield | ✓ |
| Condition: Passenger Side/Light Scuffing<50mm | ! | | |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ! |
| | | Beading: Crack/Fair Use Wear<50mm | |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | | Right Hand Side Mirror | ✓ |
| Body: Paint Chip-off < 5mm | ! | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ! | Left Rear Alloy/ Rim | ! |
| Rim: Alloy Face/ Scuff < 50mm | | Rim: Alloy Face/ Scuff < 50mm | |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |

| | |
|------------------|---|
| Panel Condition | |
| Rear Trunk Panel | ⚠ |
| Scratch < 50mm | |

Engine & Transmission

| | | |
|--------------------------------|---|----------------------|
| Engine | | |
| Engine Body | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓ |
| Radiator Condition | ✓ | Radiator Coolant ✓ |
| Battery | | |
| Battery Terminal & Tightness | ✓ | |
| Fuel System | | |
| Fuel Cap | ✓ | Fuel Tank ✓ |
| Transmission Operation | | |
| Gear Shifting | ✓ | Drive Axle ✓ |
| Transmission Fluid | ✓ | |

Steering, Suspension & Brakes

| | | |
|------------------------|---|-------------------------|
| Steering | | |
| Steering wheel | ✓ | |
| Brake System | | |
| Parking Brake | ✓ | Brake Master Cylinder ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid ✓ |
| Pedals | ✓ | |
| Suspension | | |
| Shock Absorbers | ✓ | |

Electricals, Controls & Lights

| | |
|------------|---|
| Keys | |
| Master Key | ✓ |
| Door Locks | |

| | | | |
|--------------------------------|---|---|---|
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System Audio Inputs: Not Working | ! |
| Lights | | | |
| Headlight | | | |
| Left: Light Scuff Marks < 50mm | ! | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger Not Working | ! |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears | ! | Manual Seat Movement | ✓ |

| | | | |
|---------------------------------|---|-------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |
| Front Left Door: Light Scuffing | | | |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE