



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 KIA SORENTO**

**EX | 125,924 KM**

VIN: KNAPH8157K5518075

**Car highlights**



**Panoramic Roof**

This car has a panoramic roof



**Cruise control**

Cruise control to drive with ease & comfort



**Apple play**
















Enjoy your drive with apple play



**Amazing Comfort**

Power driver seat, Memory Seats & more





Basic Details

 Kilometers	125924	 Specs	Yes
 Engine	2.4L	 Option Type	Full Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	KNAPH8157K5518075		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Traction Control	
Front Camera		Side Camera	

Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Comfort &amp; Convenience</b>			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	✓	Power Folding Mirrors	✓
Ventilated Seat	✓	Power Tailgate/ Power Trunk	✓
Rear Defogger	✓	Central Armrest	✓
MagSafe Wireless Charging	✓	Automatic Headlights	✓
 <b>Exteriors</b>			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
LED Headlights	✓	HID Headlights	✓
 <b>Performance</b>			
Differential Locks	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓





# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door Panel: Low Visibility Dent < 30mm	
Rear left door		Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Light Scuffing<50mm	
--------------------	--	---	--

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	!	Right Running Board	✓
Front Left Sill Trim: Minor Scuffing < 80mm			
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	!	Monogram	✓

Light Scuffing < 50mm

Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body

Underbody: Minor Cover Fair Use Wear



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s) Remote Functions Not Responding	!
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Seat Heaters	✓	Memory Seats	✓
--------------	---	--------------	---

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet		Headliner	!
Front Right Floor Mat: Smudge/Burn/Crack	!	Rear Left: Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<45%	LHS Rear Tyre	<75%
RHS Front Tyre	<45%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE