



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 HYUNDAI ACCENT

GL | 62,585 KM

VIN: MALC741C1LM171469

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort









Power driver seat


Basic Details

 Kilometers	62585	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALC741C1LM171469		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Central Armrest			
 Safety & Security			

Parking Sensors Rear	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Handle: Paint Chip-off < 5mm



Rear left door

Panel: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Rear right door

Handle: Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip < 8mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition


Roof 

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar
Low Visual Dent < 30mm 

Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 


Running Board Condition

Left Running Board 

Right Running Board 

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip
Mark<5mm, Passenger Side/Stone Chip
Mark<8mm 

Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 


Right Side Mirror 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition 

Wheel Arch 

Wheel cover
Front Right: Face/ Scuffs < 50mm, Edge/ 

Scuffs < 80mm

Antenna



Grill Condition



Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Acid Marks/ Bird Dropping < 5mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger

Extensive Wear Of Strip



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel Color Faded		Sunvisor	
Seat Upholstery Passenger Seat: Minor Smudge/Cracks		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE