



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 MAZDA CX 9 GT | 51,247 KM

VIN: JM5TCAWY9M0415085

## **Car highlights**



### Supercharger/turbocharger

This car has a Supercharger/turbocharger



#### **Cruise control**

Cruise control to drive with ease & comfort



### Apple play


Enjoy your drive with apple play



### **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Fog Light Front	<b>✓</b>	Running Lights	<b>✓</b>
Rear Bumper Spoiler	<b>✓</b>	HID Headlights	•
Safety & Security			
Parking Sensors Rear	<b>✓</b>	Reverse Camera	<b>~</b>
Blind Spot Monitor	<b>✓</b>	Traction Control	<b>✓</b>
Airbag Curtain Shield	<b>✓</b>	Airbag Driver Front	<b>✓</b>
ABS	<b>✓</b>	Central Locking	<b>✓</b>
Child Safety Locking	<b>✓</b>		
<b>□ Entertainment</b>			
Bluetooth Player	<b>✓</b>	Apple Play	•
Android Auto Play	<b>✓</b>	USB Charging Port	<b>✓</b>
Infotainment System	<b>✓</b>	USB player	<b>✓</b>
Performance			
Crawl Function			

### **150 Point Detailed Inspection Report**


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>~</b>	Right A Pillar	•
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar Light Scuffing < 50mm	!
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	<b>✓</b>		
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Chip < 5mm	!	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	<b>✓</b>



Keys			
Master Key	<b>✓</b>	Spare Key(s) Fair Use Wear	(!)
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>~</b>		
Controls	<b>✓</b>	Cruise Control	•
Infotainment Display	<b>✓</b>	Engine Sensors	<b>✓</b>
OBD Connector	•	Radar (If Equipped)	<b>✓</b>
Navigation System  Condition: Available - SD Card Missing	(!)	Music System	•
Sunroof Operation			
Sunroof	<b>✓</b>		
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Turn Signal Lights	<b>✓</b>
Daylight Running Lights	<b>✓</b>	License Plate Light	<b>✓</b>
Fog Lights	<b>✓</b>		
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	~
Front Right AC Vent	<b>~</b>	Heater	~
Rear Blower Switch	<b>✓</b>		
Parking Sensors	<b>✓</b>	Rear Defogger	•
USB Charging Port	<b>✓</b>	Power/ Manual Windows	<b>✓</b>





# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE