



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 HYUNDAI TUCSON

GL | 58,025 KM

VIN: TMAJ281B8LJ999256

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat




Basic Details

 Kilometers	58025	 Specs	Yes
 Engine	2.4L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	TMAJ281B8LJ999256		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	

Steering Mounted Audio Controls	✓	Power Folding Mirrors	✓
Central Armrest	✓		
 Safety & Security			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Performance			
Hill Descent Control	✓		
 Entertainment			
Bluetooth Player	✓	USB player	✓


150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door
Handle: Paint Chip-off < 5mm 


Front right door
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door
Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 


Rear right door
Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Fenders Condition

Left Fender
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm 

Right Fender
Condition: Paint Chip-off < 5mm, Low Visual Dent < 30mm, Light Scuffing < 50mm 

Quarter Panels Condition

Left Quarter Panel
Condition: Light Scuffing<50mm 

Right Quarter Panel 

Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper
Rear Bumper: Chip< 8mm, Light Scuffing < 80mm 

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk
Door Trim: Light Scuffing < 50mm 

Trunk conditon

Trunk 

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Low Visual Dent < 50mm	!
Right B to C Pillar Beading	✓	Left C Pillar Low Visual Dent < 30mm	!
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	!	Right Running Board Rear Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Chip < 5mm	!	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		


Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger			
Extensive Wear Of Strip	!	USB Charging Port	✓

Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use Wear



Steering Wheel



Sunvisor



Seat Upholstery

Passenger Seat: Minor Smudge/Cracks



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE