



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 NISSAN ALTIMA

S | 99,505 KM

VIN: 1N4BL4A9XLC193416

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort









Power driver seat

Basic Details

| | | | |
|--|-------------------|---|-----------------------|
|  Kilometers | 99505 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | 1N4BL4A9XLC193416 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
|  Safety & Security | | | |
| Parking Sensors Rear |  | Reverse Camera |  |

| | | | |
|--|---|---------------------|---|
| Traction Control |  | Airbag Driver Front |  |
| ABS |  | Central Locking |  |
| Child Safety Locking |  | | |
|  Entertainment | | | |
| Bluetooth Player |  | Infotainment System |  |
| USB player |  | | |
|  Exteriors | | | |
| Halogen Headlights |  | | |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|------------------------------------|---|--|---|
| Front left door |  | Front right door |  |
| | | Panel: Light Scuffing < 50mm | |
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Scratch < 50mm | | Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm, Low Visual Dent < 30mm | |

Fenders Condition

| | | | |
|------------------------|---|---------------------------|---|
| Left Fender |  | Right Fender |  |
| Condition: Dent < 30mm | | Right Fender: Dent < 30mm | |

Quarter Panels Condition

| | | | |
|--------------------|--|---------------------|--|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|--|---------------------|--|


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

Hood Condition

| | |
|------------------------------------|---|
| Hood |  |
| Bonnet: Low Visibility Dent < 30mm | |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

| | | | |
|--------------------------------------|---|--|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ! | Right Running Board | ! |
| Front Left Sill Trim: Scratch < 80mm | | Front Right Sill Trim: Light Scuffing < 80mm | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ! | Right Hand Side Mirror | ✓ |
| Body: Scratch < 50mm | | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ! | Left Rear Alloy/ Rim | ✓ |
| Rim: Alloy Edge/ Scuff < 80mm | | | |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ✓ |
| Rim: Alloy Edge/ Scuff < 80mm | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

| | | | |
|-----------------------|---|---------------------|---|
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |

| | | | |
|--------------------------------|---|-------------|---|
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |
| Front Left Door: Fair Use Wear | | | |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE