



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 HONDA PILOT

LX | 52,422 KM

VIN: 5FNYP5842LB700114

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat




Basic Details

| | | | |
|--|--------------------------|---|----------------------------|
|  Kilometers | 52422 |  Specs | Yes |
|  Engine | 3.5L |  Option Type | Mid Option |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Grey |
|  Interior Trim | Fabric Trim |  Number of Airbags | 10 Airbags |
|  Seating Capacity | 8 Seats |  Number of keys | 2 Keys |
|  VIN number | 5FNYP5842LB700114 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
|  Exteriors | | | |

| | | | |
|--|---|----------------------|---|
| Fog Light Front |  | Running Lights |  |
| Rear Bumper Spoiler |  | Halogen Headlights |  |
| HID Headlights |  | | |
|  Safety & Security | | | |
| Parking Sensors Front |  | Parking Sensors Rear |  |
| Reverse Camera |  | Traction Control |  |
| Airbag Curtain Shield |  | Airbag Driver Front |  |
| ABS |  | Central Locking |  |
| Child Safety Locking |  | | |
|  Entertainment | | | |
| Bluetooth Player |  | USB Charging Port |  |
| Infotainment System |  | USB player |  |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Handle: Light Scuffing < 50mm



Front right door

Handle: Paint Chip-off < 5mm



Rear left door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm



Right Fender

Condition: Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm



Right Quarter Panel

Condition: Light Scuffing<50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|-----------------------------|---|-----------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |

Running Board Condition

| | | | |
|--------------------|---|---------------------|---|
| Left Running Board | ✓ | Right Running Board | ✓ |
|--------------------|---|---------------------|---|

Windshield Condition

| | | | |
|------------------|---|-----------------|---|
| Front Windshield | ✓ | Rear Windshield | ✓ |
|------------------|---|-----------------|---|

Structural Assessment

| | | | |
|------------------------------|---|------------------|---|
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |

Rear View Mirror Condition

| | | | |
|---|---|------------------------|---|
| Left Hand Side Mirror Body: Chip < 5mm | ⚠ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |

Alloy Wheel/ Rim

| | | | |
|----------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|------------|---|---------|---|
| Wheel Arch | ✓ | Antenna | ✓ |
|------------|---|---------|---|

| | | | |
|--|---|----------|---|
| Grill Condition Light Scuffing < 50mm | ⚠ | Monogram | ✓ |
|--|---|----------|---|

Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

| | | | |
|-------------------------|---|---------------------|---|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Cigarette Lighter: Cigarette Lighter Missing | ⚠ |
|--------------------------------|---|---|---|

| | | | |
|------------------------|--|----------------------|--|
| Cup Holder | | Glove Box | |
| Steering Wheel | | Sunvisor | |
| Seat Upholstery | | Manual Seat Movement | |
| Seat Belts | | Head Rest | |
| Door Controls And Trim | | Grab Handle | |
| Carpet | | Headliner | |
| Rear View Mirror | | Toolkit | |

Tyres

Tyres Condition

| | | | |
|----------------------------|------------------|---------------------------|------|
| Left Hand Side Front Tyre | | Left Hand Side Rear Tyre | |
| Right Hand Side Front Tyre | | Right Hand Side Rear Tyre | |
| Spare Tyre | | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | No spare tyre | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE