



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 NISSAN X TRAIL

S | 63,098 KM

VIN: JN1BT2MU2LW018657

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth




Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat












Basic Details

 Kilometers	63098	 Specs	Yes
 Engine	2.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JN1BT2MU2LW018657		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 Safety & Security			
Parking Sensors Rear		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Exteriors			
Running Lights		Rear Bumper Spoiler	
Halogen Headlights			
 Entertainment			
Bluetooth Player		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility



Dent < 30mm, Paint Chip-off < 5mm

Rear left door

Panel: Low Visual Dent < 30mm, Light



Scuffing < 50mm, Paint Chip-off < 5mm

Rear right door

Panel: Low Visual Dent < 30mm, Light



Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light



Scuffing < 50 mm

Right Fender

Condition: Light Scuffing < 50mm, Low Visual



Dent < 30mm

Quarter Panels Condition

Left Quarter Panel

Condition: Paint Faded



Right Quarter Panel

Condition: Light Scuffing<50mm, Low Visual



Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing



< 50mm

Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board		Right Running Board	
Front Left Sill Trim: Minor Scuffing < 80mm	!	Front Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror		Right Hand Side Mirror	✓
Body: Light Scuffing < 50mm	!		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel Scratch < 50mm	⚠		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder		Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			
Seat Upholstery		Manual Seat Movement	
Rear Left Seat: Minor Smudge/ Crack			
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE