



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 NISSAN X TRAIL

SV | 119,784 KM

VIN: JN1BT2MM4HW000023

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat




Basic Details

| | | | |
|--|-------------------|---|-----------------------|
|  Kilometers | 119784 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Mid Option |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | JN1BT2MM4HW000023 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Central Armrest |  | Automatic Headlights |  |
|  Exteriors | | | |
| Fog Light Front |  | Roof Rails |  |

| | | | |
|--|---|----------------------|---|
| Running Lights | ✓ | Halogen Headlights | ✓ |
|  Performance | | | |
| Hill Descent Control | ✓ | Differential Locks | ✓ |
|  Safety & Security | | | |
| Reverse Camera | ✓ | Traction Control | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|-----------------|---|--|---|

| | | | |
|----------------|---|---|---|
| Rear left door |  | Rear right door Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm |  |
|----------------|---|---|---|

Fenders Condition

| | | | |
|-------------|---|--|---|
| Left Fender |  | Right Fender Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|-------------|---|--|---|


Quarter Panels Condition

| | | | |
|---|---|---|---|
| Left Quarter Panel Condition: Low Visual Dent<30mm, Chip<5mm |  | Right Quarter Panel Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm |  |
|---|---|---|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|--|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |
|--|---|

Hood Condition

| | |
|---|---|
| Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|---|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

| | | | |
|---|---|-----------------------------|---|
| Roof Condition | | | |
| Roof | ✓ | | |
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Driver Side/Scuffing, Passenger Side/Light Scuffing<50mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |

| | | | |
|----------------------------|---|-----------------------|---|
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ✓ | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid | ✓ |

Steering, Suspension & Brakes

| | | | |
|-----------------------|---|------------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Brake Master Cylinder | ✓ | Brake Disc & Brake Pad | ✓ |
| Brake Fluid | ✓ | | |
| Pedals | ✓ | | |

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE