



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 MAZDA 3

S | 47,053 KM

VIN: JM7BN1SZ9K1259066

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat


Basic Details

 Kilometers	47053	 Specs	Yes
 Engine	1.6L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7BN1SZ9K1259066		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	USB player	✓
 Exteriors			
Halogen Headlights	✓		





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door Panel: Paint Chip-off < 5mm	

Fenders Condition

Left Fender Condition: Paint Chip-off < 5mm		Right Fender	
--	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood Bonnet: Paint Chip-off < 5mm	
--------------------------------------	---

Trunk Condition

Trunk	
-------	---





Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror			
Body: Paint Chip-off < 5mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE