



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 INFINITI Q30

STD | 92,205 KM

VIN: SJKDH5CP9KA003845

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	92205	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Leather Trim	 Number of Airbags	9 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	SJKDH5CP9KA003845		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Automatic Headlights	
 Exteriors			
Fog Light Front		Running Lights	

Halogen Headlights			
 Safety & Security			
Lane Departure Warning System		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Collision Warning System		Traction Control	
Airbag Curtain Shield		Airbag Knees	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Performance			
Paddle Shift			
 Entertainment			
Bluetooth Player		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



Rear left door

Panel: Paint Chip-off < 5mm, Dent < 30mm, Scratch < 50mm



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm



Right Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Paint Chip-off < 5mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof 

Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear, Fair Use Wear 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 

Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 

Running Board Condition

Left Running Board Condition: Scratch < 80mm 

Right Running Board Condition: Light Scuffing < 80mm, Light Scuffing < 80mm 

Windshield Condition

Front Windshield 

Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

Rear View Mirror Condition

Left Hand Side Mirror 

Left Side Mirror 

Right Side Mirror 

Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm 

Left Rear Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm 

Right Front Alloy/ Rim
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/
Scuff < 80mm



Right Rear Alloy/ Rim
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/
Scuff < 80mm



Wheel Arch



Wheel cover



Grill Condition
Light Scuffing < 50mm



Monogram



Window Glass



Wiper
Operation: Cover Missing



Panel Condition
Rear Trunk Panel
Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals 

Suspension

Shock Absorbers 

 **Electricals, Controls & Lights**

Keys

Master Key 
Button Faded

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Camera 

Lights

Headlight 
Left: Low Brightness lamps

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

Daylight Running Lights 
Right DRL: Low Brightness

License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling 

AC Switch 
Button(s) Faded

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Blower Switch			
Fair Use Wear			
Rear Defogger		USB Charging Port	
Power/ Manual Windows		Seat Heaters	

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Glove Box		Cigarette Lighter: Cigarette Lighter Missing, Minor Ashtray Fair Use Wear	
Sunvisor		Steering Wheel	
Manual Seat Movement		Seat Upholstery	
Head Rest		Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	
Grab Handle		Seat Belts	
Headliner		Door Controls And Trim	
Toolkit		Carpet	
		Rear View Mirror	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE