



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN SENTRA**

**S | 106,369 KM**

VIN: MNTBB7A97L6067083

## **Car highlights**



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**
















Power driver seat



### **Airbag safety**











Airbag Driver Front

## Basic Details

 Kilometers	<b>106369</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MNTBB7A97L6067083</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Comfort &amp; Convenience</b>			
Rear Defogger		Central Armrest	



## Entertainment

Bluetooth Player



USB player



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Panel: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Acid Marks/ Bird Dropping < 5mm,  
Scratch < 50mm

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm

### Fenders Condition

Left Fender



Right Fender



Condition: Scratch < 50mm

Right Fender: Scratch < 50mm

### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm

Condition: Dent < 30mm, Paint Chip-off <  
5mm, Scratch < 50mm

### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing  
< 50mm



### Trunk Condition

Trunk



Trunk conditon

Trunk



### Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar Condition: Dent < 30mm, Scratch < 50mm	!
Left B Pillar Trim Light Scuffing	!	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Scratch < 50mm	!

Running Board Condition

Left Running Board Front Left Sill Trim: Scratch < 80mm	!	Right Running Board Front Right Sill Trim: Light Scuffing < 80mm	!
--	---	---	---

Windshield Condition

Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm, Passenger Side/Light Scuffing<50mm	!	Rear Windshield	✓
---	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Right: Face/ Scuffs < 50mm, Edge/	!

Scuffs < 80mm

Antenna



Grill Condition



Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing





Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Right Door: Light Scuffing		Grab Handle	
Carpet Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear		Headliner Rear Left: Smudge/Disfiguration	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE